NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201	INSPECTION REPORT	U.S. NUCLEAR REGULATO AND COMPLIANCE INSPECTION	DRY COMMISSION
1. LICENSEE/LOCATION INSPECTED: Smiths Detection 30 Hook Mountain Road Pinebrook, NJ 07058-9798 REPORT Nos 2005-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECT	ON
030-32123	29-28620-01	May 10, 2005	
LICENSEE:			
The inspection was an examination of the act Nuclear Regulatory Commission (NRC) rules of procedures and representative records, int X	s and regulations and the condition terviews with personnel, and obsets, no violations were identified. Excribed to you by the inspector as cive action was or is being taken, on, were satisfied.	nse as they relate to radiation safety and to compliance with a sof your license. The inspection consisted of selective expressions by the inspector. The inspection findings are as a soft and the remaining criteria in the NRC Enforcement Policy flowing requirement(s) and Corrective Action(s):	examinations follows:
		w and/or attached, were in violation of NRC requirements subject to posting in accordance with 10 CFR 19.11.	and are
I hereby state that, within 30 days, the actions corrective actions is made in accordance with	s described by me to the inspecton the requirements of 10 CFR 2.2	ctive Actions for Item 4, above. or will be taken to correct the violations identified. This star 101 (corrective steps already taken, corrective steps which on response to NRC will be required, unless specifically rec	will be taken,
LICENSEE'S REPRESENTATIVE NRC INSPECTOR Joseph Nick		/RA/	5/10/05