

# RI - DNMS Licensee Event Report Disposition

Licensee: Green Bay Packaging Inc 00-120 Bal 90  
 Event Description: Intermittent light on shutter indicator Ohmatt  
 License No: 45-25268-0 Docket No: 03033271 MLER-RI: 2005-009  
 Event Date: 1-18-05 Report Date: \_\_\_\_\_ HQ Ops Event #: 41345

### REPORTING REQUIREMENT

<input type="checkbox"/> 10 CFR 20.1906 Package Contamination	<input type="checkbox"/> 10 CFR 30.50 Report
<input type="checkbox"/> 10 CFR 20.2201 Theft or Loss	<input type="checkbox"/> 10 CFR 35.3045 Medical Event
<input type="checkbox"/> 10 CFR 20.2203 30 Day Report	<input type="checkbox"/> License Condition
<input type="checkbox"/> Other _____	

### 2. REGION I RESPONSE

<input type="checkbox"/> Immediate Site Inspection	Inspector/Date	
<input type="checkbox"/> Special Inspection	Inspector/Date	
<input type="checkbox"/> Telephone Inquiry	Inspector/Date	
<input type="checkbox"/> Preliminary Notification/Report	<input type="checkbox"/> Daily Report	
<input checked="" type="checkbox"/> Information Entered in RI Log	<input checked="" type="checkbox"/> Review at Next Inspection	
Report Referred To: _____		

### REPORT EVALUATION

<input checked="" type="checkbox"/> Description of Event	<input checked="" type="checkbox"/> Corrective Actions
<input checked="" type="checkbox"/> Levels of RAM Involved	<input type="checkbox"/> Calculations Adequate
<input checked="" type="checkbox"/> Cause of Event	<input type="checkbox"/> Additional Information Requested from Licensee

### MANAGEMENT DIRECTIVE 8.3 EVALUATION

<input type="checkbox"/> Release w/Exposure > Limits	<input type="checkbox"/> Deliberate Misuse w/Exposure > Limits
<input type="checkbox"/> Repeated Inadequate Control	<input type="checkbox"/> Pkging Failure > 10 rads/hr or Contamination > 1000x Limits
<input type="checkbox"/> Exposure 5x Limits	<input type="checkbox"/> Large# Indivs w/Exp > Limits or Medical Deterministic Effects
<input type="checkbox"/> Potential Fatality	<input type="checkbox"/> Unique Circumstances or Safeguards Concerns
If any of the above are involved:	
<input type="checkbox"/> Considered Need for IIT	<input type="checkbox"/> Considered Need for AIT
Decision/Made By/Date: _____	

### MANAGEMENT DIRECTIVE 8.10 EVALUATION (additional evaluation for medical events only)

<input type="checkbox"/> Timeliness - Inspection Meets Requirements (5 days for overdose / 10 days for underdose)
Medical Consultant Used-Name of Consultant/Date of Report: _____
<input type="checkbox"/> Medical Consultant Determined Event Directly Contributed to Fatality
<input type="checkbox"/> Device Failure with Possible Adverse Generic Implications
<input type="checkbox"/> HQ or Contractor Support Required to Evaluate Consequences

### SPECIAL INSTRUCTIONS OR COMMENTS

Public Inspector Signature: [Signature] Date: 1/25/05  
 Non-Public Branch Chief Initials: [Signature] Date: 1/25/05

Location of File: G:\Reference\Blank Forms\2004 LER FORM.wpd

Rev. 02/01/05

PUBLIC: SISP REVIEW COMPLETE FME



LN 45-25268  
01

RECEIVED  
REGION 1  
DN

03033271

**Green Bay Packaging Inc.**

Winchester Coated Products Division

05 FEB 14 P1:14

February 7, 2005

**United States Regulatory Commission  
Region 1  
475 Allen Dale Road  
King of Prussia, Pennsylvania 19406-1415**

**Issue: Intermittent light on shutter indicator Ohmart OD-120 Bal 90**

**To Whom It May Concern:**

**This letter is a follow up to the phone report made to Steve Sardin on January 18, 2005, event # 41345.**

**Mid morning on the 18<sup>th</sup> we experienced a situation where the indicator light for shutter position blinked a couple of times. We checked the gauge with our survey meter and found shutter was working properly and that the switch for the light indicator seemed to be the issue. I called Honeywell Measurex and asked for a service technician to come in and check the unit out and order a new switch. The technician arrived on 1/27/05 and installed a new switch; the old switch was tested and found to be intermittent. Unit is working properly and no further issues have occurred.**

**Thank You,**

*Michael P. Dickey*  
**Michael P. Dickey RSO  
Green Bay Packaging Inc.  
Winchester Coated Products**

**cc: Tom Schibly**

SPECIALISTS IN COATED SELF-ADHESIVE MATERIALS

285 Park Center Drive ■ P.O. Box 3568 ■ Winchester, VA 22604-2575 ■ Phone: 703-678-2600, 800-750-8800

FAX: 703-678-2611