

AmerGen Energy Company, LLC Oyster Creek US Route 9 South, P.O. Box 388 Forked River, NJ 08731-0388 www.exeloncorp.com

An Exelon Company

GL 97-02

July 11, 2005 2130-05-20147

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555 - 0001

> Oyster Creek Generating Station Facility Operating License No. DPR-16 NRC Docket No. 50-219

Subject:

Monthly Operating Report - June 2005

Enclosed is the June 2005 Monthly Operating Report for Oyster Creek Generating Station. The content and format of information submitted in this report is in accordance with the guidance provided by Generic Letter 97-02.

If any further information or assistance is needed, please contact David Fawcett at 609-971-4284.

Sincerely,

James & Randich C. N. Swenson

Vice President, Oyster Creek Generating Station

CNS/DIF Enclosure

cc:

S. J. Collins, Administrator, USNRC Region I

P. S. Tam, USNRC Senior Project Manager, Oyster Creek

R. J. Summers, USNRC Senior Resident Inspector, Oyster Creek

File No. 05002

TEN

## **OPERATING DATA REPORT**

DOCKET NO.	50-219			
UNIT NAME Oyster Creek 1				
DATE	July 08, 2005			
<b>COMPLETED BY</b>	Roger B Gayley	-		
TELEPHONE	(609) 971-4406			
REPORTING PERI	OD: June 2005			
1. Design Electric	cal Rating	650.00		
	endable Capacity (MWe-Net)	619.00		
•				

3.	Number of Hours the Reactor was Critical	This Month 675.97	<u>Yr-to-Date</u> 4,298.97	<u>Cumulative</u> 230,778.47
	Number of Hours Generator On-line	666.85	4,289.85	226,460.30
5.	Reserve Shutdown Hours	0.00	0.00	918.20
6.	Net Electrical Energy Generated (MWHrs)	401,539.00	2,674,996.00	129,916,720.0

## **UNIT SHUTDOWNS**

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason 1	Method of Shutting Down 2	Cause & Corrective Action Comments
1F08	06/01/2005	F	53.15	Н	3	06/01/2005 - CAP O2005-2337. Reactor scrammed due to apparent load reject. First Energy closed in bad lightning arrestors inside the Manitou Substation. This caused a voltage transient on the 230KV system which lead to a generator lockout (from a loss of two of three 230KV lines exiting the substation) and subsequent turbine trip and reactor scram.

SUMMARY: The planned losses for June, which include operating the plant with margin to the license limit and condenser losses, totaled 6,628.9 MWhrs. A forced outage (1F08) caused by a grid disturbance occurred June 1 at 21:09 Hours and ended June 4 at 02:18 hours. The 53.15-hour forced outage was beyond Plant Management's control, therefore, the lost generation associated with the outage (38,655 MWhrs) is not included in the Forced Loss Rate calculation

1 Reason:

A Equipment Failure (Explain)

**B** Maintenance or Test

C Refueling

D Regulatory Restriction

E Operator Training & License Examination

Administration

Operational Error (Explain)

H Other (Explain)

Method:

- 1 Manual
- 2 Manual Trip/Scram 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)