

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**



1. LICENSEE The Heart Health Center REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 03033709		4. LICENSE NUMBER(S) 24-26530-01	5. DATE(S) OF INSPECTION May 27, 2005
6. INSPECTION PROCEDURES USED 87130		7. INSPECTION FOCUS AREAS 03.01 - 03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Terese Matti, Chief NMT	4. TELEPHONE NUMBER 314/993-6969
------------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: **May 2010**

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee was a medical clinic authorized by the license to use any byproduct material permitted by 10 CFR 35.100 and 35.200 at two authorized locations, 620 Maple Valley Drive, Farmington, MO, and at 450 North New Ballas Road, Suite 170, St. Louis, MO. Licensed activities at Suite 170, 450 North New Ballas Road, were conducted in the cardiology suite, as indicated on the license. The cardiac nuclear medicine department was staffed with four nuclear medicine technologists (NMT). The NMTs routinely conduct 10-20 Cardiolite cardiac studies each day. The licensee received unit doses as ordered from a local licensed nuclear pharmacy. All waste was held for decay-in-storage (DIS) or returned to the nuclear pharmacy as a limited quantity, excepted shipment.

Performance Observations

During the inspection, the licensee's NMT demonstrated/discussed: (1) survey meter use; (2) package check-in procedures and wipe test counting; (3) dosimetry; (4) dose calibrator checks; (5) safe use and handling; and (6) security.