

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Arnett Clinic, LLC REPORT 2005-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-36652	4. LICENSE NUMBER(S) 13-32535-01	5. DATE(S) OF INSPECTION July 12, 2005	
6. INSPECTION PROCEDURES USED 87131		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM 2120	2. PRIORITY G3	3. LICENSEE CONTACT Rodney Dunseath, MD., RSO	4. TELEPHONE NUMBER 765-448-8000
---------------------------	--------------------------	---	--

Main Office Inspection Next Inspection Date: **July 2006**

Field _____

Temporary Job Site _____

PROGRAM SCOPE

INITIAL INSPECTION

This currently inactive medical program has not used or received licensed material since the license was issued on October 22, 2004.

In subsequent discussions with Dr. Dunseath, it was revealed that the program may be active in about one year. Currently, the licensee has contracted with Medical Consultants Imaging Co., d/b/a/ Alliance Imaging, Co., Canton, OH (NRC License 34-26286-02), to perform mobile nuclear medicine imaging services on-site twice per week (typically Mondays and Tuesdays). See IR 03035070/2005001.

The proposed hot-lab and imaging areas for the clinic were toured during the inspection and found to be as indicated on submitted license documentation.

Observations and confirmatory survey measurements taken of the proposed use areas did not indicate the presence of licensed material.

Since byproduct material is not currently possessed, another inspection should be conducted in one year as stated above.

