

RADIOGRAPHY AND NDE SOLUTIONS
H.C. 80, BOX 6785
DORADO, PR 00646

License No. 52-25615-01

August 1, 2005

U.S. Nuclear Regulatory Commission

ATTN: Document Control Desk
Washington, D.C. 20555

Mr. John D. Kinneman

SUBJECT: REPLY TO A NOTICE OF VIOLATION

The reason for the first violation of not conducting a leak test in camera containing depleted Uranium was that when I took over the RSO position for this Company I was not aware that there was record on file containing the leak test for this camera until the inspection. I try to contact the previous RSO to ask if he had any record that was not filed but any luck trying to contact him. The corrective step I have taking was to perform a leak test next day of the NRC Inspection. To corrective step taking to avoid further violations was that I created a spread sheet with all the dates that shows when the next leak test needs to be done. I posted this in the office and temporary job site so the personnel will be aware of this also. The date when this compliance was achieved was on May 27, 2005. The reason for the second violation was that it was over looked when the radiographer and radiographer assistant audit was due. The corrective step taking was that I also created a spread sheet with all radiographer's and assistant radiographer name and when the next audit due date to prevent this. All of the personnel's audits are up to date.

Sincerely,



Victor O. Morales
Radiation Safety Officer

Enclosure:
Response to Violation

Cc:
Jim Schmidt
Health Physicist
United States Nuclear Regulatory Commission

IE07