

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Stan Huber, INC REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 999900012	4. LICENSE NUMBER(S) IL-01013-01	5. DATE(S) OF INSPECTION 7/15/05	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3225	2. PRIORITY 3	3. LICENSEE CONTACT Joie Ziller	4. TELEPHONE NUMBER 815/485-6161
<input type="checkbox"/> Main Office Inspection		Next Inspection Date: 7/2008	
<input type="checkbox"/> Field Office			
<input checked="" type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

Licensee is a service provider doing work at the Childrens Hospital in Minneapolis, Minnesota. Licensee provides calibration services and performs linearity and constancy checks of the dose calibrators.

Performance Observations

The inspector interviewed the technician performing the dose calibrator checks. The technician appeared to be knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.