

on wood  
marks

- Outage Manager  
Emergency Response, Site Badge

PETE Habiger <sup>horst</sup>  
~~XXXXXXXXXXXXXXXXXXXX~~

→ pressure in PRT to rupture a rupture disc; Ex 6

nominal → considering drain PRT before rupture disc ruptures?  
w 200°

→ status of tampering procedure? TSC has lead  
→ ERDS status? ~~yes~~ still not working

→ Unit 2 outage work activities on hold?

↓ Brian  
Talk to ~~Brian~~ Lockett  
Pete Marzetta

S/G safety lift sequence

Rm 205 in  
training center

termination criteria for alert? Getting containment pressure  
down

containment sump in-leakage

PZR safety or PORV? code safety not sure on PORV  
newer lifts

Waiting on MS1

6hr LCO → code safety

Believe in <sup>12hr</sup> 3.7.1.1

solid state channel "A" inop.

Cont pressure high 36hr shutdown Spoc

Report to Phoke

Call Silas

Information in this record was deleted  
in accordance with the Freedom of Information  
Act, exemptions b6  
FOIA-2005-0007

Portion Ex 6

H/1

Event  
Response  
Team

APRIL 18 MDA

- April 17 Event

• 0830 Rx trip  $\frac{1}{2}$  SI injection (low S/G B header) <sup>Instrument. panel</sup>  
signal (logic card)

• manual start other half

• Steam line safety open - caused ALERT (steam line unisoleble)

• "C" S/G open

• PORV's open "B" is leaking closed block valve for PORV

rough 1-2 gal/min leak

• "C" charging pump leak - packing leak?

• "B" should have full SI?

• TAFW - trip?

• Main Steam Iso signal isolate ADV