

R

March 3, 1980

MEMORANDUM FOR: L. B. Higginbotham, Assistant Director, Division
of Fuel Facility and Materials Safety Inspection, IE

THRU: A. B. Davis, Chief, Fuel Facility and Materials
Safety Branch

FROM: W. L. Fisher, Chief, Fuel Facility Projects
and Radiation Support Section

SUBJECT: TI2600/1

A summary report of an inspection conducted at Combustion Engineering, Inc.,
is attached.

W. L. Fisher, Chief
Fuel Facility Projects and
Radiation Support Section

Attachment: as stated

L-1

OFFICE	RIII	RIII	RIII			
SURNAME	<i>Wm for</i> Peck/11	<i>Wm for</i> Fisher	<i>Wm for</i> Davis			
DATE	3/3/80					

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Docket No. 70-36

License No. SNM-33

Licensee: Combustion Engineering, Inc.
Hematite, Missouri

Inspection dates: February 26-27, 1980

Inspector(s): C.C. Peck

Scope of inspection: The licensee's actions in response to IE Bulletin 79-19 were examined in accordance with the inspection requirement of TR 2600/10.

Summary of findings and proposed enforcement action:

No items of noncompliance were identified.

Package inspection results:

Number of packages opened: One (If none, explain why)

Results: A 55-gallon drum containing contaminated potassium hydroxide solution solidified with cement, according to the licensee, was opened. The drum contained a solid concrete mass.