NRC FORM 591M PART 1			U.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2.20:				
SAFETY INS	PECTION REPORT ANI	COMPLIANCE	NSPECTION	
		2. NRC/REGIONAL OFFICE		
InstroTek - N.E.		11 C. M. J. L. Brandston, Commission		
78 South M ain Street		U.S. Nuclear Regulatory Commission		
Newtown, CT 06470		Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT Nos 2005-001		King of Prussia,	Permisyivama 19400-14	, 10
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTI	ON
030-35611	06-30610-01		8. 30+31	2005
LICENSEE:			,	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed. 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):				
4. During this inspection certain of you	ur activities, as described belov	v and/or attached, wer	e in violation of NRC requirem	ents and are
being cited. This form is a NOTICE OF	eguires the U	CINSTE TO	coordance with 10 CFR 19.11.	nnvelly
10 CFR 20.1101 (c) requires the licensee to at least annually review their entire vadiation protection program. The				
The licensee will complete a review of their program in				
30 days. Documentation will be maintained.				
License Condition is requires a lock on the sauce or its				
I have the five fore gauses were not locked not				
licensee has not revewed their program in the last 3 years. The licensee will complete a review of their program in 30 days. Documentation will be maintained. License Condition 17 requires a lock on the sauge or its container when in storage. The gauges were not locked, nor in their container whom in their storage norm. The licensee will purchase locks + lock all sauges when in storage.				
purchase well + acc	all alles with	VIN ZION	apc.	
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of				
corrective actions is made in accordance with the date when full compliance will be achieved). I ur	ne requirements of 10 CFR 2.20	01 (corrective steps als	ready taken, corrective steps v	which will be taken,
Title Prin	nted Name		Signature	Date
REPRESENTATIVE Philip C	स्थिः।। ८	(hely	Paletta	8/31/05
NRC INSPECTOR Kathy Doice Mod	les	of. A	Modes	831.05

NRC FORM 591M PART 1 (10-2003)

P:\Inspection\InstroTek591M PART 1.wpd

NRC-002