

Office Memorandum • UNITED STATES GOVERNMENT

TO : Harold L. Price, Director, Division of
Licensing and Regulation, Headquarters

DATE: AUG 10 1959

FROM : Robert W. Kirkman, Director
Inspection Division, NYOO

SUBJECT: TRANSMITTAL OF LICENSE COMPLIANCE FOLLOW-UP INSPECTION REPORT -
10 CFR 30 - 40

SYMBOL: INS:PRN

Transmitted herewith is the following "follow-up" and initial inspection report:

ALUMINUM COMPANY OF AMERICA
Aluminum Research Laboratories
Freeport Road
New Kensington, Pennsylvania

License No. 37-7653-2 (follow-up)
License No. C-4724 (initial)

No items of noncompliance were noted under Part 40 inspection.

The following item of noncompliance was noted under Part 30 inspection:

License No. 37-7653-2

20.203 "Caution signs, labels, and signals"
(f)(4) "Containers" - in that the waste drums in which were stored millicurie amounts of byproduct material, although labeled with a sign "Caution - Radioactive Material" and prescribed symbol, failed to show the kind, quantity and date of measurement of the quantity of radioactive material each contained. (See Item C, paragraph 10 of report details.)

The above item of noncompliance, which was also noted during the initial inspection, was called to the attention of Mr. Lewis, who expressed willingness to correct the condition noted.

(continued)

General L. B. ...

...

...

...

...

...