Combustion Engineering, Inc.

ATTN: Mr. J. A. Rode, Plant Manager

Hematite Nuclear Fuel Manufacturing

P. O. Box 107

Hematite, MO 63047

Dear Mr. Rode:

SUBJECT: U.S. NRC INSPECTION REPORT NO. 70-36/91-201

The Nuclear Regulatory Commission (NRC) conducted a routine inspection of your facility's material control and accounting safeguards program on February 11-14, 1991. The scope and results of the inspection are summarized in the Inspection Report Summary (Enclosure 1). Areas examined during the inspection are described in the Inspection Report Details (Enclosure 2).

The inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations of activities in progress. At the conclusion of the inspection, the findings were discussed with you and members of your staff. Within the scope of this inspection, no violations or deviations were identified.

Under the provisions of Section 2.790(d), reports containing information related to a licensee's material control and accounting program are exempt from public disclosure. Accordingly, the enclosed Inspection Report Details will not be placed in the Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original Signed by The fore S. Sherr

Theodore S. Sherr, Chief Domestic Safeguards Branch Division of Safeguards and Transportation, NMSS

Enclosures: As stated

cc: w/encl.

H. E. Eskridge

C. R. Waterman A. E. Scherer

J. F. Conant

C. B. Brinkman

Distribution:

NRC File Center

Docket File 70-36 PDR w/o encl 2

NSIC w/o encl 2

Case File

RJackson

TPham

SGDB c/f

SGDB r/f

MWilliams

GNelson

RBurnett

RMilstein

MMessier, LFDB w/o encl 2

GMFrance, RIII

ESuarez

CHaughney, IMSB

OFC:SGDB : SGDB// : SGDB GBN NAME: GNelson/jV: RMilstein : ESwarez :DJKasuk : DATE: 03/9/91 : 03/ /91 : 03/9//91 : 03/6/91 :03/ 6/91

OFFICIAL RECORD COPY

9103110399 app.

The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2.790(d).

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF NUCLEAR MATERIAL SAFETY AND SAFEGUARDS

Report No:

70-36/91-201

License No:

SNM-33

Safeguards Group:

III

Licensee:

Combustion Engineering, Inc. P.O. Box 107, Highway P

Hematite, Missouri 63047

Inspection at:

Hematite, Missouri

Inspection Conducted:

February 11 through 14, 1991

Inspectors:

G. B. Nelson, MC&A Physical Scientist

Date Signed

03-04-91

Physical Security and MC&A Licensing

and Inspection Section Domestic Safequards Branch

6.5 6 -11 R. I. Milstein, MC&A Physical Scientist Date Signed Physical Security and MC&A Licensing

and Inspection Section Domestic Safequards Branch

Approved by:

D. J. Kasun, Section Leader

Physical Security and MC&A Licensing

and Inspection Section Domestic Safeguards Branch

SUMMARY

Scope:

The inspection consisted of a routine unannounced MC&A safeguards inspection in the areas of internal controls, measurement systems, records and reports, and management meetings-entrance and exit interviews. Inspection procedures used were 85405, 85407, 85415, and 30703.

Results: Within the areas inspected, no violations, deviations, or declining performance were identified. One open item from a previous inspection

was continued, and a new follow-up item was opened.

REGION 3 INSPECTION FEE SUMMARY REPORT MANHOURS EXPENDED PER COMPLETED INSPECTION QUARTERLY SUMMARY - OPERATING FACILITIES PERIOD COVERING: 09/22/91 TO 12/28/91 MATERIALS LICENSES

RUN DATE: 12/05/95 PAGE: 1

SNM-33

LICENSEE NAME: COMBUSTION 3300 STATE HEMATITE	ENG ROA	INEERING, DP	INC.	MO 63047	D	OCKET #:	07000036	FACILITY	/ NAME:	COMBUSTION	ENGINEERING,	IN
INSPECTION REPORT NUMBERS:	*	91202	*	*	*	*		* *	•	*	*	*
BOUTTHE PERSON	- -			Ţ.	Ξ.			* ·		<u>.</u>	*	-
ROUTINE EFFORT	*	21.0	 k	*	*	*		* *	- Ir	*	*	*
PREP./DOCUM. INSPECTION	*	29.0	*	*	*	*		* *	٠	*	*	*
SUBTOTAL ROUTINE SUB. ROUTINE FEE	\$	50.0 5750.00										
	•	0.000	_						_		_	
REACTIVE EFFORT	*		* •	*	*	*		* *	.	*	*	*
PREP./DOCUM.	*	0.0	* •	*	*	*		* *		*	*	*
INSPECTION	*	0.0	~ #	*	*	*		* *		*	*	*
SUBTOTAL REACTIVE SUB. REACTIVE FEE	\$	0.0										
REPORT TOTALS FEE PER REPORT	\$	50.0 5750.00										
	•			TOTAL THERE	27704	A	F350 0	•				
TOTAL ROUTINE FEE TOTAL REACTIVE FEE	\$ _	5750.00 0.00		TOTAL INSPEC			5750.0 0.0					
TOTAL INSPECTION FEE	\$	5750.00		TOTAL	FEE	\$	5750.0	0				

^{***} PLEASE NOTE: A RATE OF \$116/\$123 WAS USED TO CALCULATE THE FEES FOR DATES ON OR AFTER 6/24/1995