

From: Kenneth Jenison *RT*
To: Jeff Laughlin, Joseph Schoppy, Robert Fretz, Sc...
Date: Mon, Nov 13, 2000 1:50 PM
Subject: Control Room Pressurization Testing at Salem

Good Morning,

I am chasing an issue at Salem that occurred in 1996 or 1997 involving the performance of control room ventilation pressurization testing. Apparently the testing involved a lineup of doors adjoining the control room. I did a word search of the 1996 and 1997 inspection reports on the local DRP R/inspect drive and Adams and found not discussion. I checked FSAR amendments and also found no discussion of an inability to maintain control room pressure post accident with or without any special line up. Can you steer me in the right direction.

Branch 3 owes an input to an allegation close out letter (RI-2000-A-0127) by COB Friday.

CC: David Meyer, David Vito, James Linville, Richar...

335
F