

DSER Section Table of Contents

| Page, Section, and Paragraph | DSER Text | Suggested Revision | Justification | Category |
|------------------------------|---|---|---------------|----------|
| Page 6-v | | Add the following text 2.1.4 Conclusion page.....2-25 | | 3 |
| Page 6-v | 2.3.1.1 Class 1 Piping/eomponents System... | 2.3.1.1 Class 1 Piping/ C omponents System... | | 3 |
| Page 6-vii | 2.5.1.6 High-voltage Insulators | 2.5.1.6 High- V oltage Insulators | | 3 |
| Page 6-viii | 3.0.3.3 AMPs That Are Not Consistent with or Not Addressed in the GALL Report | 3.0.3.3 AMPs That Are Not Consistent W ith or Not Addressed in the GALL Report | | 3 |
| Page 6-viii | 3.1.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . | 3.1.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . | | 3 |
| Page 6-viii | | Add the following text 3.1.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Recommended....3-139 | | 3 |
| Page 6-viii | | Add the following text 3.1.3 Conclusion...3-166 | | 3 |

| Page, Section, and Paragraph | DSER Text | Suggested Revision | Justification | Category |
|------------------------------|---|---|---------------|----------|
| Page 6-viii | | Add the following text 3.2.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended....3-171 | | 3 |
| Page 6-viii | 3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . | 3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . | | 3 |
| Page 6-viii | 3.3.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended . . | 3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . | | 3 |
| Page 6-ix | 3.5.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . . | 3.5.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . . | | 3 |
| Page 6-ix | 3.5.2.3 AMR Results That Are Not Consistent with or Not Addressed in the GALL Report | 3.5.2.3 AMR Results That Are Not Consistent With or Not Addressed in the GALL Report | | 3 |

| Page, Section, and Paragraph | DSER Text | Suggested Revision | Justification | Category |
|------------------------------|---|---|---------------|----------|
| Page 6-ix | 3.6.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . . | 3.6.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . . | | 3 |
| Page 6-ix | 3.6.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended . . . | 3.6.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Recommended . . . | | 3 |
| Page 6-ix | | Add the following text 3.7 Conclusion for Aging Management...3-303 | | 3 |
| Page 6-xii | | Add the following text 4.5 Loss of Preload...4-60 4.5.1 Containment Tendon Loss of Preload...4-60 4.5.1.1 Summary of Technical Information in the Application...4-60 4.5.1.2 Staff Evaluation 4-60 4.5.1.3 FSAR Supplement...4-63 | | 3 |

| Page, Section, and Paragraph | DSER Text | Suggested Revision | Justification | Category |
|------------------------------|--------------------------------------|--|---------------|----------|
| Page 6-xii | 4.8.1.4 Conclusion 4-70 | 4.8.1.4 Conclusion 4-71 | | 3 |
| Page 6-xii | | Add the following text 4.9 Conclusion for Time-Limited Aging Analyses...4-71 | | 3 |
| Page 6-xx | STP Steam Trap | STP- Sewage Treatment Plant | Clarification | 2 |