NRC FORM 591M PAF	RT 1			J.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2.201	SAFETY INSPE	CTION REPORT AI	ND COMPLIANC	E INSPECTION	
1. LICENSEE/LOCATION INSPECTED:  Capital X-Ray Services, Inc. 2133 South 49th West Avenue Tulsa, Oklahoma			2. NRC/REGIONAL OFFICE  USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	_
030-05933 LICENSEE:		35-11114-01		September 19, 200	5
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X					
	n 30 days, the actions desc	s Statement of Correcti ribed by me to the inspector w equirements of 10 CFR 2.201	Il be taken to correct the vi	olations identified. This staten	
date when full compliand Title LICENSEE'S	,	rstand that no further written re ted Name	•	uired, unless specifically reque gnature	ested.  Date
REPRESENTATIVE					
NRC INSPECTOR	Christi Maier, He	ealth Physicist	1	RA/	09/19/2005