

October 11, 2005

Mr. J. A. Stall  
Senior Vice President, Nuclear and  
Chief Nuclear Officer  
Florida Power and Light Company  
P.O. Box 14000  
Juno Beach, Florida 33408-0420

SUBJECT: BULLETIN 2004-01, "INSPECTION OF ALLOY 82/182/600 MATERIALS USED IN THE FABRICATION OF PRESSURIZER PENETRATIONS AND STEAM SPACE PIPING CONNECTIONS AT PRESSURIZED-WATER REACTORS," RESPONSE FOR THE TURKEY POINT NUCLEAR PLANT (TAC NOS. MC3520 AND MC3521)

Dear Mr. Stall:

On May 28, 2004, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2004-01, "Inspection of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized-Water Reactors," to the industry. This Bulletin informed addressees that current methods of inspecting the pressurizer penetrations and steam space piping connections fabricated from Alloy 82/182/600 materials may need to be supplemented with additional measures (e.g., bare-metal visual inspections) to detect pressurizer penetration and steam space piping connection flaws or leakage. The Bulletin requested that these addressees provide the NRC with information related to the materials of construction, the inspections that have been performed, and the inspections which will be performed to verify the integrity of the pressurizer penetrations and steam space piping connections. By letter dated July 27, 2004, Florida Power and Light Company (the licensee) provided its response to Bulletin 2004-01 for the Turkey Point Nuclear Plant, Units 3 and 4.

By this letter, the licensee provided its responses to items 1a, 1b, 1c, and 1d of the Bulletin. These responses described the materials used in the fabrication of pressurizer penetrations and steam space piping connections at Turkey Point Units 3 and 4. When describing the materials used in the fabrication of the pressurizer penetrations and steam space piping connections, the licensee reported that none of the materials used in the fabrication of the pressurizer penetrations and steam space piping were Alloy 82/182/600 materials. Therefore, there is no specific inspection program for Alloy 82/182/600 materials for the pressurizer other than meeting the requirements of Section XI of the American Society for Mechanical Engineers, *Boiler and Pressure Vessel Code*.

Given the licensee's response to items 1a, 1b, 1c, and 1d of the Bulletin, the NRC staff no longer requires a specific response for Turkey Point Units 3 and 4 for item 2 of the Bulletin, which requested that licensees report the results of their next scheduled inspection of Alloy 82/182/600 pressurizer penetrations and steam space piping connections.

J. Stall

-2-

The NRC staff has completed its activities associated with the review of your response to Bulletin 2004-01 for Turkey Point Units 3 and 4 and finds your response acceptable. Please contact me at (301) 415-3974 if you have any questions on this issue.

Sincerely,

*/RA/*

Brendan T. Moroney, Project Manager, Section 2  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-250 and 50-251

cc: See next page

J. Stall

-2-

The NRC staff has completed its activities associated with the review of your response to Bulletin 2004-01 for Turkey Point Units 3 and 4 and finds your response acceptable. Please contact me at (301) 415-3974 if you have any questions on this issue.

Sincerely,

*/RA/*

Brendan T. Moroney, Project Manager, Section 2  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-250 and 50-251

cc: See next page

Distribution:

PUBLIC  
PD II-2 r/f  
RidsNrrPMBMoroney  
RidsNrrPMEBrown  
RidsNrrPMTColburn  
RidsNrrLABClayton  
RidsNrrDlpmLpdii2  
RidsNrrDlpmLpdi  
RidsNrrDlpmLpdii  
RidsNrrDlpmDpr  
RidsNrrDlpm  
MMitchell  
EAndruszkiewicz  
RidsOgcRp  
RidsAcrsAcnwMailCenter  
RidsRgn2MailCenter (JMunday)

ADAMS Accession No.: ML052720590

NRR-106

OFFICE	PM/PDII-2	LA/PDII-2	D/PDI	SC/PDII-2
NAME	BMoroney	BClayton	CHolden by memo dated	MMarshall
DATE	10/ 05 /05	10/ 03 /05	08/ 12 /05	10/ 11 /05

**OFFICIAL RECORD COPY**

Mr. J. A. Stall  
Florida Power and Light Company

cc:

M. S. Ross, Managing Attorney  
Florida Power & Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420

Marjan Mashhadi, Senior Attorney  
Florida Power & Light Company  
801 Pennsylvania Avenue, NW.  
Suite 220  
Washington, DC 20004

T. O. Jones, Site Vice President  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW. 344th Street  
Florida City, FL 33035

County Manager  
Miami-Dade County  
111 Northwest 1 Street, 29th Floor  
Miami, Florida 33128

Senior Resident Inspector  
Turkey Point Nuclear Plant  
U.S. Nuclear Regulatory Commission  
9762 SW. 344<sup>th</sup> Street  
Florida City, Florida 33035

Mr. William A. Passetti, Chief  
Department of Health  
Bureau of Radiation Control  
2020 Capital Circle, SE, Bin #C21  
Tallahassee, Florida 32399-1741

## **TURKEY POINT PLANT**

Attorney General  
Department of Legal Affairs  
The Capitol  
Tallahassee, Florida 32304

Michael O. Pearce  
Plant General Manager  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW. 344th Street  
Florida City, FL 33035

Walter Parker  
Licensing Manager  
Turkey Point Nuclear Plant  
9760 SW 344th Street  
Florida City, FL 33035

Mark Warner, Vice President  
Nuclear Operations Support  
Florida Power and Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420

Mr. Rajiv S. Kundalkar  
Vice President - Nuclear Engineering  
Florida Power & Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420

Mr. Craig Fugate, Director  
Division of Emergency Preparedness  
Department of Community Affairs  
2740 Centerview Drive  
Tallahassee, Florida 32399-2100