NRC FORM 591M PAR (10-2003) 10 CFR 2.201		PECTION REPORT AN		S. NUCLEAR REGULATO	RY COMMISSION
LICENSEE/LOCATION INSPECTED:     Metropolitan Cardiology Consultants, LLC     104 Chestnut Street     Ridgewood, New Jersey 07450  REPORT Nos 2005-001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S)	5	. DATE(S) OF INSPECTION	ON
03035587	,	29-30600-01		September 8, 2005	
The inspection was an ex Nuclear Regulatory Comr of procedures and repres  X 1. Based on the 2. Previous vio 3. The violation identified, non-r NUREG-1600,	mission (NRC) rules and a entative records, interview e inspection findings, no validation(s) closed. (s), specifically described epetitive, and corrective a to exercise discretion, we	conducted under your license regulations and the conditions vs with personnel, and observational violations were identified.  It to you by the inspector as no ction was or is being taken, ar	of your license. The inspect tions by the inspector. The inspector in the inspector.	ifety and to compliance with ion consisted of selective exinspection findings are as formal f	n the xaminations ollows:
being cited. Thi	s form is a NOTICE OF \	activities, as described below a /IOLATION, which may be sulful to the s	ve Actions for Item 4	e with 10 CFR 19.11.	
corrective actions is made	e in accordance with the rewill be achieved). I unde	equirements of 10 CFR 2.201 rstand that no further written reted Name	(corrective steps already tak esponse to NRC will be requ	en, corrective steps which	will be taken,
NRC INSPECTOR	Stephen Hammar	ın	/R	A/	09/08/2005