NRC FORM 591M PAR (10-2003)	RT 1		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201	SAFETY INSPEC	TION REPORT AN	ID COMPLIANCI	EINSPECTION	
Genencor International, Inc 925 Page Mill Road Palo Alto, California 94304  REPORT NUMBER(S) 05-001			2. NRC/REGIONAL OFFICE  USNRC Region IV 611 Ryan Plaza Drive Arlington, Texas 76011-4005		
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-36487		04-27770-01		September 26, 200	5
LICENSEE:				, ,	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X					
cited. This form	n is a NOTICE OF VÍOLAT and Corrective Actions)	ctivities, as described below a ION, which may be subject to	posting in accordance with	n 10 CFR 19.11.	nd are being
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.  Title Printed Name Signature Date					
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Lawrenc	e Donovan	//F	RA//	9 /26 /2005