

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Cardiology Center of North Jersey 1030 Clifton Avenue Clifton, NJ 07013		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT NUMBER(S)			
3. DOCKET NUMBER(S) 030-35176	4. LICENSE NUMBER(S) 29-30528-01	5. DATE(S) OF INSPECTION September 21, 2005	

(Continued)

Appendix J of the application dated July 22, 1999, requires that, in the event of a minor spill of liquids, licensee employees are required to report the incident to the Radiation Safety Officer (RSO).

Contrary to the above, on July 12, 2005, the licensee failed to conduct its program in accordance with the statements, representations, and procedures contained in the application dated July 22, 1999, and the letters dated September 11, 1999, and February 1, 2000. Specifically, a minor spill of liquid, containing Tc-99m, occurred and the licensee's technician did not inform the RSO.

After residual contamination from the spill was identified the following day by another technician, the RSO was notified regarding the spill. The licensee's corrective actions for this event included reviewing the current policy and procedure regarding spills with the nuclear cardiology staff.