(10-2003)	{ 1			U.S. NUCLEAR REGULATO	THY COMMISSION
SAFET	Y INSPECTION	REPORT AND	COMPLIANCE INS	PECTION	
1. LICENSEE/LOCATION INSPECTED: Consumers Energy 135 WTM-1 S+ Tackson, MI 49 201-2276 REPORT 2005 201			2. NRC/REGIONAL OFFICE US NKC Kig III 2443 Warrowith Kl Suite 210 List, II 6082		
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		Set 13, 2005	SPECTION
Nuclear Regulatory Comof procedures and representation 1. Based on the 2. Previous vio 3. The violation non-repetitive, a	nemission (NRC) rules an sentative records, interverse inspection findings, no lation(s) closed. (s), specifically described and corrective action was lion, were satisfied.	d regulations and the con iews with personnel, and violations were identified. d to you by the inspector as or is being taken, and the	ditions of your license. The observations by the inspecto	iation safety and to compliar inspection consisted of selector. The inspection findings a being cited because they we Enforcement Policy, NURECTS) and Corrective Action(s):	ctive examinations are as follows:
L cited. This form	nspection certain of your a is a NOTICE OF VIOLAT and Corrective Actions)	activities, as described bel FION, which may be subjec	ow and/or attached, were in vert to posting in accordance w	riolation of NRC requirements ith 10 CFR 19.11.	s and are being
corrective actions is mad date when full complianc Title LICENSEE'S REPRESENTATIVE	30 days, the actions des e in accordance with the e will be achieved). I und	cribed by me to the inspect requirements of 10 CFR 2	.201 (corrective steps alread ten response to NRC will be	 above. violations identified. This significant of the state of the sta	ch will be taken, equested. Date
NRC INSPECTOR	1 (2, 42,4		1 10-1		10/13/05

NRC FORM 591M PART 1 (10-2003)

NRC FORM 591M PART 3 (10-2003) 10 CFR 2-201		Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION		U.S. NUCLEAR REGULATORY COMMISSION	
1. LICENSEE	.		2. NRC/REGIONAL OFFICE		
Consumers E	nergy 2005-001		Region III		
3. DOCKET NUMBER(S)	<u> </u>	4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-04868		21-08606-03		October 13, 2005	
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS			
87126		03.01 - 03.07			
		SUPPLEMENTAL INSP	ECTION INFORMATION		
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT		4. TELEPHONE NUMBER	
03320	1	Russell Rotta		517/788-1901	
X Main Office I	nspection		Next Inspection Date:	10/06	

PROGRAM SCOPE

The licensee is a radiographer located in Jackson, Michigan with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has ten full time radiographers and is in possession of six 660 exposure devices.

Performance Observations

At the time of the inspection, licensee was performing radiography within the cell located at its office. The cell was equipped with all the required warning devices and was posted in accord with the regulations. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low 500 mRem on average.

No violations of requirements were noted.

Temporary Job Site