

From: Ngoc Le
To: David Dellario
Date: 10/5/05 10:57AM
Subject: RE: Draft RAIs for NMP Amended LRA - Batch 3 [10-5-2005]

David:

Attached is the 3rd set of the staff RAIs for the NMP amended LRA review.

Please review and let me know when you would like to have a telecon to discuss the draft with the staff reviewer.

Then we will docket the RAIs. Normally you will have 30 days to respond; however, the sooner you provide the responses, the better for the staff.

tommy

CC: Pei-Ying Chen; Peter.Mazzaferro@Constellation.com; Rajender Auluck

Mail Envelope Properties (4343E9D2.627 : 0 : 566)

Subject: RE: Draft RAIs for NMP Amended LRA - Batch 3 [10-5-2005]
Creation Date: 10/5/05 10:57AM
From: Ngoc Le

Created By: NBL@nrc.gov

Recipients	Action	Date & Time
Constellation.com	Transferred	10/05/05 10:58 AM
David.Dellario (David Dellario)		
Peter.Mazzaferro CC (Peter.Mazzaferro@Cons		

nrc.gov		
OWGWPO01.HQGWDO01	Delivered	10/05/05 10:57 AM
PYC CC (Pei-Ying Chen)	Opened	10/05/05 11:33 AM
RCA CC (Rajender Auluck)	Opened	10/05/05 12:11 PM

Post Office	Delivered	Route
OWGWPO01.HQGWDO01	10/05/05 10:57 AM	Constellation.com nrc.gov

Files	Size	Date & Time
MESSAGE	1012	10/05/05 10:57AM
ALRA_PYChen_DRAI_10_4_05.wpd		7218 10/05/05 10:56AM

Options

Auto Delete: No
Expiration Date: None
Notify Recipients: Yes
Priority: Standard
Reply Requested: No
Return Notification: None

Concealed Subject: No
Security: Standard

To Be Delivered: Immediate
Status Tracking: Delivered & Opened

**Draft RAI FOR THE AGING MANAGEMENT OF AUXILIARY SYSTEMS FOR
NMP1 and NMP2 amended LICENSE RENEWAL APPLICATIONS**

EMEB

3.3 Aging Management of Auxiliary Systems

General RAI

1. a-RAI 3.3.2-1

One-Time Inspection (OTI) is appropriate where either an aging effect is not expected to occur but there is insufficient data to completely rule it out, or the aging effect is expected to occur very slowly so as not to affect the component intended function. In the Amended LRA (ALRA), the applicant proposed to use OTI program to manage aging effects for various materials exposed to various environments for majority of the components in the following two systems: (a) ALRA Table 3.3.2.A-14, NMP1 Radioactive Waste System, and (b) ALRA Table 3.3.2.B-14, NMP2 Floor and Equipment Drains System.

Please: **(1)** Explain from system characteristics standpoint, why the OTI program [rather than periodic inspections] is proposed to manage the aging effects for those material/environment combinations having OTI as the sole AMP in these two systems; and

(2) Justify the use of OTI program for the following cases:

- (A)** In ALRA Table 3.3.2.A-14, Aging Effect Requiring Management (AERM) of cracking for Wrought Austenitic Stainless Steel (WASS) Heat Exchangers exposed to air, moisture or wetting, temperature greater or equal to 140 degree F, and for WASS valves exposed to treated water, temperature greater or equal to 140 degree F but less than 212 degree F.
- (B)** In ALRA Table 3.3.2.A-14, AERM of loss of material (LOM) for carbon or low alloy steel (yield strength less than 100 ksi), or WASS valves, and piping and fittings exposed to Demineralized Untreated Water (DUW).
- (C)** In ALRA Table 3.3.2.A-14, AERM of LOM for carbon or low alloy steel (yield strength less than 100 ksi) valves exposed to either the DUW, low flow, or treated water, temperature greater or equal to 140 degree F but less than 212 degree F.
- (D)** In ALRA Table 3.3.2.B-14, AERM of cracking for WASS Drainers exposed to treated water, temperature greater or equal to 140 degree F but less than 212 degree F.
- (E)** In ALRA Table 3.3.2.B-14, AERM of LOM for aluminum pump, or carbon or low alloy steel (yield strength less than 100 ksi) strainers exposed to raw water.

ATTACHMENT

System Specific RAI

2. a-RAI 3.3.2.A-5-1

What does the Note "K" represent for Heat Exchangers, and valves and dampers in Table 3.3.2.A-5? Please explain why the LOM was not identified as an AERM for WASS Heat Exchangers exposed to DUW similar to the WASS Heat Exchangers in Table 3.3.2.A-14.