

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Samuel Suede, M.D.
285 Grand Avenue, 5 Patriot Center
Englewood, NJ 07631

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

REPORT Nos 03036664/2005-001

3. DOCKET NUMBER(S)

030-36664

4. LICENSE NUMBER(S)

29-30955-01

5. DATE(S) OF INSPECTION

10/12/2005

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☒ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 20.1501 requires that each licensee make or cause to be made, surveys that are reasonable may be necessary for the licensee to comply with the requirements of this part, and are reasonable under the circumstances to evaluate the potential radiological hazards.

10 CFR 20.2001 requires that licensed material be disposed of only by authorized means.



Contrary to the above, on October 11, 2005, the licensee placed licensed material in a biohazard container not meant for the disposal of licensed material.

Specifically, on October 12, 2005, the inspector identified that Tc-99m-contaminated objects had been placed in a biohazard container not meant for radioactive waste.

The licensee committed to surveying the biohazard container at the end of each day of use to ensure that radioactive waste was not put in the container.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	SAMUEL SUEDE MD		10/12/05
NRC INSPECTOR	Steven R. Courtemanche		10/12/2005