

NR
From: Rick Ennis
To: Alan Wang; Allan Barker; Allen Howe; Anthony McMurtray; Cheng-lh Wu;
Christopher Grimes; David Terao; Diane Screnci; Donna Skay; Eric Leeds; Gene Imbro; James
Clifford; John Jolicoeur; Kamal Manoly; Neil Sheehan; Richard Barrett; Scott Burnell; Tae Kim;
Terrence Reis; Thomas Scarbrough; William Beckner; William Ruland
Date: 4/16/04 11:11AM
Subject: Fwd: FYI CRACKS FOUND IN VY DRYER

#21

CC: Cliff Anderson; David Pelton; Tad Marsh

E-24

From: Cliff Anderson *RT*
To: Raymond Lorson
Date: 4/16/04 10:42AM
Subject: Fwd: FYI CRACKS FOUND IN VY DRYER

fyi

CC: David Pelton; Donald Florek; Rick Ennis

From: James Wiggins *IRI*
To: Jim Dyer; Samuel Collins
Date: 4/16/04 10:40AM
Subject: FYI CRACKS FOUND IN VY DRYER

FYI Some preliminary info re: VY dryer cracks....

Entergy is considering a press release that covers the fact that, with GE, it identified 4 cracks in the dryer during visual inspections conducted this outage. Entergy says that the 4 cracks are in low-stress, low-steam flow, areas of the dryer, and not in the areas affected at the EPU plants.

Two of the cracks, located in weld areas, were ground-out and repaired; the other two are not accessible.

We're continuing to monitor this situation...we had an ISI inspection this week that looked at this issue as part of our planned inspection activities connected with NRR's EPU review.

More to come when info is available.

Jim

CC: Brian Sheron; Hubert Miller; Richard Borchardt; Tad Marsh