

U.S. NUCLEAR REGULATORY COMMISSION		Date: 11/10/2005
TELEPHONE CONVERSATION RECORD		Time: 3:30 PM
Mail Control or Report No(s).	137481	License No(s). 47-00260-02 Docket No(s). 03006652
Name of Licensee:	Union Carbide Corporation	
Name of Participant(s):	Michael Boyd	
Telephone No.	304-747-7974	
Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small>	RAI, response to information on October 28, 2005 letter.	
Summary:	I stated there needed to be some additional information associated with the response letter dated October 28, 2005. Specifically some of the model numbers were not able to be located on sealed registry and some items might be generally licensed. The dose rates on Building 747 was listed as mR/hr and needs to be corrected. The liquid scintillation detector reported only in 0 cpm and the data did not indicate that it could detect in the C-14 or H-3 range. They need to state that there was no licensed radioactive material at the Institute Plant, that they never had licensed material at that site, and that it should be removed from the license. The licensee explained many of these items on the phone and would need to look up some of the items.	
Action Required:	Mr. Boyd would make statements associated with the above and get me information to answer my questions.	
Document Availability:	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date	
Prepared & SISP Review Completed By:	/ RA / Dennis Lawyer Date: 11/10/2005	