

November 16, 2005

Mr. Norman A. Kent, Manager
Transportation Licensing and Regulatory Compliance
Westinghouse Electric Company
Nuclear Fuel
Columbia Fuel Site
P. O. Drawer R
Columbia, South Carolina 29250

SUBJECT: RECEIPT OF APPLICATION - TERMINATION OF REVIEW

Dear Mr. Kent:

This refers to your application dated October 18, 2005, requesting an amendment to Certificate of Compliance No. 9297, for the Model Nos. Traveller STD and Traveller XL.

This letter is to inform you that during the acceptance review, the U.S. Nuclear Regulatory Commission staff found deficiencies in your application which prevents us from accepting it for technical review. These deficiencies include not providing sufficient design information about the apparent new loose rod pipe shipping package in Drawing 10006E58, sheet 2, Revision 3. Also, Section 1.2.1.4 of the Safety Analysis Report was not revised to describe this new loose rod pipe shipping package.

If you have any questions regarding this matter, we would be pleased to meet with you and your staff. I may be contacted at (301) 415-8531.

Sincerely,

/RA/

Stewart Brown, Senior Project Manager
Licensing Section
Spent Fuel Project Office
Office of Nuclear Material Safety
and Safeguards

Docket No. 71-9297
TAC No. L23915

Mr. Norman A. Kent, Manager
Transportation Licensing and Regulatory Compliance
Westinghouse Electric Company
Nuclear Fuel
Columbia Fuel Site
P. O. Drawer R
Columbia, South Carolina 29250

SUBJECT: RECEIPT OF APPLICATION - TERMINATION OF REVIEW

Dear Mr. Kent:

This refers to your application dated October 18, 2005, requesting an amendment to Certificate of Compliance No. 9297, for the Model Nos. Traveller STD and Traveller XL.

This letter is to inform you that during the acceptance review, the U.S. Nuclear Regulatory Commission staff found deficiencies in your application which prevents us from accepting it for technical review. These deficiencies include not providing sufficient design information about the apparent new loose rod pipe shipping package in Drawing 10006E58, sheet 2, Revision 3. Also, Section 1.2.1.4 of the Safety Analysis Report was not revised to describe this new loose rod pipe shipping package.

If you have any questions regarding this matter, we would be pleased to meet with you and your staff. I may be contacted at (301) 415-8531.

Sincerely,

/RA/

Stewart Brown, Senior Project Manager
Licensing Section
Spent Fuel Project Office
Office of Nuclear Material Safety
and Safeguards

Docket No. 71-9297
TAC No. L23915

DISTRIBUTION:

PUBLIC S. Baggett G. Bjorkman L. Campbell N. Osgood S. Williams J. Cuadrado J. Caverly M. Rahimi J. Umana
E:\Filenet\ML053200163.wpd closes TAC No. L23915 * previously concurred

OFC	SFPO	E	SFPO	c	SFPO	E	SFPO			
NAME	SBrown		DTang		MDeBose		RNelson			
DATE	11/15/05		11/ 15/05		11/15/05		11/16/05			

C = COVER E = COVER & ENCLOSURE

N = NO COPY

OFFICIAL RECORD COPY