

*JW*

### SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: <i>Complete Health Systems Hunt, MI 48532</i>		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
REPORT <i>2005-001</i>			
3. DOCKET NUMBER(S) <i>030-36714</i>	4. LICENSEE NUMBER(S) <i>21-32543-01</i>	5. DATE(S) OF INSPECTION <i>Nov. 29, 2005</i>	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura	<i>DPiskura</i>	11/29/05

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

*JN*

1. LICENSEE <b>Complete Health Systems</b> REPORT NUMBER(S) <b>2005-001</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road, Suite 210</b> <b>Lisle, IL 60532</b>	
---	--	--	--

3. DOCKET NUMBER(S) <b>030-36714</b>	4. LICENSE NUMBER(S) <b>21-32543-01</b>	5. DATE(S) OF INSPECTION <b>Nov. 29, 2005</b>
---	--	--

6. INSPECTION PROCEDURES <b>87130</b>	7. INSPECTION FOCUS AREAS <b>03.01, 03.02, 03.03, 03.04, 03.05, 03.06, 03.07, and 03.08</b>
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>02220</b>	2. PRIORITY <b>G 3</b>	3. LICENSEE CONTACT <b>Samir Elian, M.D., RSO</b>	4. TELEPHONE NUMBER <b>810.720.3891</b>
------------------------------------	---------------------------	--	--

Main Office Inspection      Next Inspection Date: Nov. 2008

Field \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

This licensee was a private practice diagnostic health care office authorized to use licensed material permitted by Sections 35.100 and 35.200. The office only provided mobile nuclear medicine services at temporary job sites. Note: the licensee did not operate a base hot lab. The licensee initiated its mobile nuclear medicine activities in January 2005 and provided nuclear cardiac imaging services to one client. The nuclear medicine studies were performed by a temporary agency technologist who performed approximately 5 diagnostic nuclear cardiology procedures daily. The licensee received unit doses from a licensed radiopharmacy. The clinic retained the services of a consulting physics group which audited the radiation safety program annually.

This inspection consisted of interviews with licensee personnel and a review of selected records. At the time of this inspection, the licensee had no prospective clients. Therefore, no temporary job site inspection was conducted at this time. The licensee anticipated that it would resume its activities in the near future, pending negotiations with a prospective client.