

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

December 22, 2005

Lt. Col. Mark Wrobel
Department of the Air Force
USAF Radioisotope Committee
HQ AFMOA/SGZR
110 Luke Ave., Suite 405
Bolling AFB, DC 20322-7050

SUBJECT: NRC INSPECTION REPORT 030-28641/05-003 and 05-004

Dear Lt. Col. Wrobel:

This letter refers to the inspections conducted on December 6-7, 2005, at Hill Air Force Base (AFB), Utah. The Master Materials License (MML) permits issued to Hill AFB which were inspected were UT-00696-00, which authorized three irradiators, and UT-30112-02, which authorized radioactive material for use in an electron tube device.

The purpose of the inspection was to determine whether activities authorized under NRC License 42-23539-01AF were conducted in accordance with NRC requirements. The NRC examined activities with respect to radiation safety and compliance and the conditions authorized under the respective permits. Within the scope of this inspection, no violations were identified; therefore, no response to this letter is required. At the conclusion of the two inspections, the findings were discussed with members of the Hill AFB staff.

Should you have any questions concerning these two inspections, please contact me at (817) 276-6552.

Sincerely,

/RA/

Rachel S. Browder, Health Physicist Nuclear Materials Inspection Branch

Docket No.: 030-28641 License No.: 42-23539-01AF

Department	of the	Air	Force
	OI LIIC		1 0100

-2-

bcc (via ADAMS e-mail distribution):
LDWert
JEWhitten
MRShaffer
RRMunoz
RSBrowder
ADGaines
USBhachu, NMSS/IMNS/MSIB
NMIB
KEGardin
RIV Materials Docket File - 5th floor

SUNSI Review Completed:	ADAMS:	Yes	□ No	Initials:	RSB3
Publicly Available	Non-Publicly Available		□ Sens	sitive	Non-Sensitive
DOCUMENT NAME: E:\File	net\ML053560338.wpd				final r:_dnm

RIV:DNMS:NMLB	RIV:DNMS:NMLB	C:NMLB
RSBrowder	ADGaines	JEWhitten
(5.4.)	(D. 4.)	(D. 4
/RA/	/RA/	/RA

OFFICIAL RECORD COPY