

U.S. NUCLEAR REGULATORY COMMISSION		Date: 12/27/05
TELEPHONE CONVERSATION RECORD		Time: 3:45 PM
Mail Control or Report No(s).	138081	License No(s). 08-30847-02 Docket No(s). 03037103
Name of Licensee:	Alfred C. Burriss, M.D., P.C.	
Name of Participant(s):	Alfred C. Burriss, M.D.	
Telephone No.	202-562-4310	
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	RAI, New License Application	
Summary:	The Maryland license MD-33-100-01 was missing a page and a page was not fully reproduced. Please send another copy of the MD-33-100-01 license. Please state the type of detectors being placed on the survey meters.	
Action Required:	Dr. Burriss will need to send in the needed information to continue processing.	
Document Availability:	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date	
Prepared & SISP Review Completed By:	/ R A / Dennis Lawyer Date: 12/27/2005	