

Morgan, Lewis & Bockius LLP  
1111 Pennsylvania Avenue, NW  
Washington, DC 20004  
Tel: 202.739.3000  
Fax: 202.739.3001  
www.morganlewis.com

**Morgan Lewis**  
C O U N S E L O R S   A T   L A W

Jay M. Gutierrez  
Partner  
202.739.5466  
jgutierrez@morganlewis.com

December 23, 2005

**VIA FEDEX**

Sara E. Brock  
Office of the General Counsel  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Re: Disclosure of Material Submitted by FirstEnergy Nuclear Operating Company in the Matter of NRC Investigation Case No. 3-2002-006

Dear Ms. Brock:

In your letter to me dated November 9, 2005, you stated that the U.S. Nuclear Regulatory Commission (NRC) is in the process of reviewing, for public release, documents submitted by FirstEnergy Nuclear Operating Company (FENOC) to the NRC's Office of Investigations (OI) in the matter of NRC Investigation Case No. 3-2002-006. According to your letter, the NRC is evaluating the information disclosed by FENOC during the course of that investigation to determine whether the information that FENOC sought to have withheld under Section 2.390(a)(4) (previously 10 C.F.R. § 2.790(a)(4)) contains trade secrets, or confidential or privileged commercial or financial information and, if so, whether such information should be withheld from public disclosure. In your letter you requested that FENOC submit affidavits supporting its previous claims that certain information disclosed to NRC during the above referenced investigation should be withheld from public disclosure due to its proprietary nature, as required by Section 2.390(b)(1).

Subsequently, on November 22, 2005, Mark Bezilla, Davis-Besse Nuclear Power Station (DBNPS) Site Vice President, received a similar letter from Christine Lipa, Chief of the NRC's Reactor Project Branch 4. Ms. Lipa requested FENOC to review documents it submitted to the NRC's Augmented Inspection Team (AIT) in mid-2002 as part of the NRC's investigation into the reactor pressure vessel head degradation at DBNPS, and to submit affidavits supporting its previous claims that certain information disclosed to NRC in those documents submitted to the AIT should be withheld from public disclosure due to their proprietary nature pursuant to Section 2.390(b)(1).

Sara E. Brock  
December 23, 2005  
Page 2

As I mentioned to you in our previous telephone conversations, most recently on December 21, 2005, FENOC has conducted an initial review of documents previously submitted to OI and the AIT and has identified those documents that may contain proprietary information. Vendors to FENOC are the owners of the vast majority of this potentially proprietary information. Therefore, in addition to reviewing its own documents for potential withholding under Section 2.390, FENOC has asked the owners of the other documents to do the same and supply FENOC with affidavits for any such document that the owner determines should be withheld from public disclosure. Attached to this letter are two tables showing the current status of each such document, including:

- the original Bates label number for each document supplied to OI;
- the file name for each document supplied to the AIT;
- a brief description of the document;
- owner of the potentially proprietary information; and
- status of the owner's review of each document and whether FENOC has received an affidavit from the owner supporting its withholding from public disclosure under Section 2.390.

We hope to have the affidavits from the various document owners by mid-January. Once FENOC receives those affidavits, we will promptly forward them to you, along with FENOC's own affidavit. Please feel free to call me if you have any questions or would like to discuss these matters further.

Sincerely,



Jay M. Gutierrez

Attachment

cc: C. Lipa  
D. Jenkins  
A. Bless  
C. Price

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
12.	12	S11-00350—00591 S11-00536—00584 S14D-00419-00449 S14D-00903—00940 S14D-01698-01728 S14D-04573-04606 S14D-06632-06664 S14D-06857-06884 S14D-07089-07120 S14D-07780-07812 S14D-08604-08634 S14J-01994-02020 S14J-02059-02108 S14M-02434-02460 S14Q-02846—02872 S14H-00645—00699 S14H-09799—09845 S14H-10904—10930 S14H-11167—11192 S14H-12042—12067 S14H-12120—12145 S14I-00159—00187 S14M-05415-05437 S14M-02434-02460 S14R-01483-01503 S14Q-00929-00946 S14Q-01771-01793 S14H-01191—01216 2S2-00520—00546	Serial 2741	Framatome	Under Review
13.	15	S14A-00723—00743 S14G-00967—00986 S14H-11074—11093 S14H-11115—11165 S14H-12147—12166 S14H-12470—12520 S14D-00106—00176 S14D-00285—00305 S14D-00450—00500 S14D-00518—00538	Serial 2747	Framatome	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item ___)	Document Bates Label	Document Description	Owner	Status
		S14D-00881—00932 S14D-00933—00953 S14D-01016—01037 S14D-01112—01163 S14D-01164—01184 S14D-01185—01211 S14D-01212—01218 S14D-01219—01260 S14D-01261—01279 S14D-01280—01296 S14D-01297—01342 S14D-01353—01404 S14F-00507—00510 S14H-06806—06811 S14I-00024—00051 S14I-00081—00089 S14I-00150 S14J-02038—02058 S14J-02116—02278 S14J-02344—02437 S14M-06188—06204 S14M-06205—06256 S14M-06292—06319 S14R-01726—01776 S14N-00955—00971 S14O-00332—00362 S14D-08845—08876 S14J-02077—02108 S14M-05773—05804 S14M-06223—06254 S11-00235—00262 S11-00272—00305			
14.	17	S14D-00501—00512 S14D-08522—08542 S14M-06320—06332 S14Q-05174—05178 S11-00316—00344	Serial 2761	Framatome	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
15.	18	S14Q-07254—07312 S14D-00795-00854 S14D-01405-01421	Serial 2777	Framatome	Under Review
16.	20	S14P-01941—02017 S14M-6769-6876 S14M-06588-06661 S14Q-00539—00569 S14P-01944—01990 2S4-00099—00172	Serial No. 1-1268	Framatome	Under Review
17.	21	S14A-00717—00718	B&WOG RV Head Repair Bulletin	Framatome	Under Review
18.	22	S14A-00719—00722	Framatome/FENOC Letter of Intent re: RPV Head Replacement	Framatome	Under Review
19.	23	S14A-00744—00759 S14A-00857—915	MRP-055 (Drafts) & Materials Re: NRC Staff's technical assessment re: "Circumferential Cracking"	EPRI	Under Review
20.	24	S14A-00760—00817	Framatome RV Head Nozzle and Weld Safety Assessment (Draft)	Framatome	Under Review
21.	25	S14A-2749—02895	EPRI materials, including correspondence with NRC re: key plant parameters for PWR cracking assessments; MRP-44	EPRI	Under Review
22.	26	S14A-00190—00194	Goyal's notes re: MRP-055; portions of MRP-055	EPRI	Under Review
23.	27	S14A-00424—00434 S14A-00530	FENOC presentation on RPV head repair/replacement costs; note on Purchase Order	FENOC	Withhold in part
24.	28	S14A-00940—00974 S14A-01054 S14A-01059—01074 S14A-01138—01348 S14A-01793—01966 S14A-02033—02249 S14A-02258—02528 S14A-02573—02745	B&W and EPRI/MRP budget and funding information	EPRI	Under Review
25.	29	S14A-02024—02028	Framatome Designs	Framatome	Under Review
26.	30	S14A-03551—03582 S14A-03629—03633 S14A-03637—03641	MRP Position Paper, marked "Draft—EPRI/MRP Internal Use only"; MRP EPRY Tables, marked proprietary by Vendor	EPRI	Under Review
27.	31	S14B-00016—00058	Contractor bid/proposal information such as work scope, schedule and cost data	FENOC	Withhold in part
28.	32	S14F-00144—00510	Miscellaneous Fyfitch Documents	Framatome	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
29.	33	S14F-00511—00515	03/30/00 e-mail from S. Fyfitch to P. Goyal (with CR)	Framatome	Under Review
30.	34	S14F-00101—00111	10/17/01 E-mail from S. Fyfitch to P. Goyal (with Framatome PowerPoint re: crack growth calculations)	Framatome	Under Review
31.	35	S14F-00116—00127 (Fyfitch)	10/21/01 e-mail from D. Killian to S. Fyfitch	Framatome	Under Review
32.	36	S14F-00130—00134	11/06/01 e-mail from D. Killian to S. Fyfitch re: growth rates and Growth Rate Curves table	Framatome	Under Review
33.	37	S14G-00895—00923	11/13/01 e-mail from C. King to distribution re: MRP's proposed section of Staff's Technical Assessment of VHP Nozzle Cracking	EPRI	Under Review
34.	38	S14G-00925—00965 S14H-09428—09477 S14H-11215—11251 S14H-09534—09573	EPRI Report TP-1006284 (MRP-48)	EPRI	Under Review
35.	39	S14G-00988—00993	Framatome Response to CR on EWR-01-0462-00	Framatome	Under Review
36.	40	S14G-00995—1000	11/12/01 e-mail from P. Goyal to distribution with Calculation Package	Framatome	Under Review
37.	42	S14G-00170—00176	11/07/01 e-mail between R. Baker (Framatome) and P. Goyal regarding calculations	Framatome	Under Review
38.	46	S14G-00286—00327	10/12/01 e-mail from D. Wuokko to distribution attaching Finite Element Gap Analysis from SIA	Framatome	Under Review
39.	48	S14G-00416—00456	11/17/01 e-mail from C. King to Distribution with Alloy 600 Level II Task Descriptions and budget sheets attached	EPRI	Under Review
40.	53	S14G-00708—00719	10/03/01 e-mail from A. Mcilree (EPRI) to P. Goyal re: PWR MRP-21; report attached	EPRI	Under Review
41.	54	S14G-00814—00854	10/05/01 e-mail from R. Bax (SIA) to P. Goyal attaching Calculation Package	Framatome	Under Review
42.	56	S14H-00617—00625 S14H-11889—11902 S14H-12326—12339 2S2-01265—01269	Framatome Document # 5013435-02 (CRDM Nozzle/Bore Dimensional Analysis)	Framatome	Under Review
43.	57	S14H-00626—00644	Draft EPRI Position Paper, RPV Head Penetration Cracking; MRP-55	EPRI	Under Review
44.	58	S14H-00705—00713	11/15/01 e-mail from S. Fyfitch to R. Baker with documents attached re: CRDM nozzle heat for B&W design nozzles	Framatome	Under Review
45.	59	S14H-00714—00845	MRP 48; 7/10/01 EPRI presentation regarding Alloy 600 ITG RPV Penetrations	EPRI	Under Review
46.	61	S14H-00887—00892	E-mail between FENOC employees re: OE12980	INPO	Under Review
47.	62	S14H-00893—00886	06/29/01 memorandum from B. Gray (Framatome) to B&WOG Materials Committee, including P. Goyal, attaching Framatome Document 51-5013435-01, titled "CRDM Nozzle/Bore Dimensional Analysis"	Framatome	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
48.	63	S14H-09575—09634 S14P-02103—02168 S14P-02294—02369 S14P-02450—02515	EPRI Report TP-1001491, Part 2 (MRP-44)	EPRI	Under Review
49.	65	S14H-09638—09655 S14H-10345—10363 S14H-10533—10554 S14H-11797—11815 S14H-12168—12186	08/14/01 & 08/13/01 e-mail from W. Gray to Duke, Entergy, FENOC re: revised safety assessment for the B&W plants and attached Framatome report	Framatome	Under Review
50.	66	S14H-09657—09792	07/03/01 e-mail from G. White (Dominion Engineering) re: MRP Response to NRC Comments on Interim Safety Assessment for RPV Head Nozzles (with attachment); various EPRI reports	EPRI	Under Review
51.	71	S14H-09953—10265	MRP-44 (EPRI Report TP1001491, Part 2; copies of MRP-48	EPRI	Under Review
52.	72	S14H-10267—10343	MRP-44	EPRI	Under Review
53.	73	S14H-10365—10513 S14H-10556—10596	MRP-48; various unidentified EPRI figures and tables	EPRI	Under Review
54.	74	S14H-10599—10663 S14H-11817—11881	Framatome's CRDM Nozzle ID Temper Bead Weld Repair Process Qualification, prepared for B&W Owners Group, Duke, Entergy, Amergen, FENOC, Florida Power Corporation Doc 77-2409-00.	Framatome	Under Review
55.	75	S14H-10666—10667	B&W Owners Group RV Head Repair Bulletin	Framatome	Under Review
56.	76	S14H-10669—10682 S14H-10812—10826	Framatome Record 51-50113435-02	Framatome	Under Review
57.	78	S14H-10688—10807 S14H-11949—11960 S14P-02018—02031	EPRI Response to NRC Staff Questions on EPRI Interim Report TP-1001491, Part 2; MRP-44; MRP-48	EPRI	Under Review
58.	80	S14H-10827—10902 S14P-02033—02098	Copies of MRP-44, Part 2	EPRI	Under Review
59.	81	S14H-11095—11114	10/22/01 memo from C. King to MRP Senior Representatives, MRP Crack Growth Rate Review Team; MRP-055 (draft)	EPRI	Under Review
60.	83	S14H-11373—11455	MRP-055 (draft, 10/19/01); MRP-44	EPRI	Under Review
61.	84	S14H-11457—11565 S14H-12341—12381	EPRI Report TP-1006284 (MRP-48); MRP-44	EPRI	Under Review
62.	86	S14H-11671—11684 2S2-01321—01343	Framatome Technical Document 08-5015881-00 re: Reactor Vessel Closure Head Replacement Davis-Besse	Framatome	Under Review
63.	87	S14H-11686—11726 S14H-11755—11795 S14H-11908—11947	Final MRP-48 (TP-1006284)	EPRI	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
64.	88	S14H-11728—11753	Draft MRP-55	EPRI	Under Review
65.	89	S14H-11883—11888 S14H-12117—12118	B&W Owners RV Head Repair Bulletins	Framatome	Under Review
66.	90	S14H-11904—11906	E-mails from W. Gray to P. Goyal and S. Fyfitch to W. Gray in 11/01 timeframe re: Davis-Besse CRDM heats	Framatome	Under Review
67.	92	S14H-11965—12030 S14H-12259—12324	MRP-44 (TP-1001491)	EPRI	Under Review
68.	94	S14H-12083—12088	09/21/01 e-mail from M. McLaughlin to P. Goyal re: attached Framatome Proposal for Davis Besse RV Head Lower Service Support Structure Access Openings Analysis (FRA-ANP Proposal # 4160076)	EPRI	Under Review
69.	95	S14H-12090—12108	08/16/01 e-mail from B. Grambau, Framatome, to P. Goyal re: attached Framatome document, "Distribution of Dimensional Fits in Davis Besse RV Head (5013435-02)	EPRI	Under Review
70.	97	S14H-12188—12240	EPRI response to 06/22/01 letter from D. Sheron re: NRC questions on EPRI Interim Report TP-1001491 (MRP-44)	EPRI	Under Review
71.	98	S14H-12242—12257	MRP-055, Part 1: B&W Tubular Products Heat (Draft)	EPRI	Under Review
72.	100	S14H-12402—12418	Framatome Engineering Information Record, #5015229-02	EPRI	Under Review
73.	101	S14H-12419—12459	Several Framatome Engineering Information Records, including #5016956-00 (Evaluation of DB-1 RV Head Penetration Repair on RCS Chemistry) and 5015229-01 (Corrosion Evaluation of DB RV Head Penetration IDB Weld Repair) and 5015231-00	EPRI	Under Review
74.	102	S14H-12461—12463	03/22/02 e-mail from Framatome to P. Goyal re: conceptual design package submittal with attached EN-DP-01230 (Major Change for EWR 02-0111-00). E-mail notes that some of the information in package is proprietary to Framatome	EPRI	Under Review
75.	103	S14H-12465—12469	Framatome Engineering Record, #5011906-00 (DB-1 RV Closure Head Flange, Dome and Assembly Stress Relieve	EPRI	Under Review
76.	104	S14H-12522—12559 2S2-00938—00972 2S2-01089—01126	SIA calculation package File Nos. W-ENTP-11Q-306	Framatome	Under Review
77.	106	S14H-12565—12571	Framatome Engineering Information Record, #50170—Draft, DB 1 Weld Repair of Boric Acid Wastage in RVH	EPRI	Under Review
78.	107	S14H-12573—12620	Framatome's Ambient ID Temper Bead Repair for B&W CRDM Nozzles, Contract No. 1231216	EPRI	Under Review
79.	109	S14H-12627—12639	06/29/01 memorandum to B&WOG Materials Committee (Exelon, First Energy, Florida Power, Entergy, Duke) re: attached Framatome document #51-5013435, titled "CRDM Nozzle/Bore Dimensional Analysis"	EPRI	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
80.	118	S14H-00916—00953 S14H-01339—01376	Calculation Package, File No. W-ENTP-11Q-306	Framatome	Under Review
81.	119	S14H-01610—01612 S14H-03044—03046	E-mails from W. Gray to P. Goyal and S. Fyfitch to W. Gray in 11/01 timeframe re: Davis-Besse heats	Framatome	Under Review
82.	120	S14H-01824—01832 S14H-01982—01990	EPRI Response to NRC Staff Questions on EPRI Interim Report TP-1001491, Part 2	EPRI	Under Review
83.	122	S14H-02085—02088 S14H-02842—02847 S14H-02855—02858	06/27/01 & 06/20/01 memorandums from P. Goyal to Distribution re: Mode 5 Reactor Vessel Head Inspection Recommendation (Reference to EPRI & B&WOG reports)	Framatome	Under Review
84.	124	S14H-02165—02174	MRP Report PRMRP-21	EPRI	Under Review
85.	130	S14H-02510—02560	MRP 2001-050 (Response to NRC Review Comments relating to PWR MRP MRP-44)	EPRI	Under Review
86.	131	S14H-02574—02585	EPRI Response to NRC Staff Questions on EPRI Interim Report TP-1001491, Part 2	EPRI	Under Review
87.	132	S14H-02766—02835	MRP-44 (TP-1001491), Part 2	EPRI	Under Review
88.	135	SH14-03013—03014	B&W Owners Group RV Head Repair Bulletin	Framatome	Under Review
89.	136	SI14-00127—00135	Circumferential Growth of Through-Wall Flaw in CRDM Nozzle	Framatome	Under Review
90.	137	SI14-00136—00154	Calculation Summary Sheet (Document Identifier 32-5015455-00)	Framatome	Under Review
91.	138	SI14-00155—00158	Results of OCONEE CRDM 3D Transient Analysis (Document No. 86-5011866-00)	Framatome	Under Review
92.	139	SI14-00159—00187	Calculation Summary Sheet (Document Identifier 32-5015455-00)	Framatome	Under Review
93.	140	SI14-000001—00020	Several e-mail between D. Killian to S. Fyfitch and other FENOC employees re: updated circ. crack growth rates (with attachments)	Framatome	Under Review
94.	141	SI14-00021—00022	E-mail between Framatome and FENOC re: heat calculations	Framatome	Under Review
95.	142	SI14-00023—00093	12/03/01 Letter from P. Goyal to Framatome re: Dominion Engineering Calculation Number C-3206-00-1, Rev. 0	Framatome	Under Review
96.	143	SI14-00094—00102	Presentation re: OD Circumferential Flaw Growth in CRDM Nozzles (with calculations)	Framatome	Under Review
97.	144	SI14-00103	10/01/01 e-mail from D. Killian to S. Fyfitch re: CRDM PWSCC thoughts for Davis-Besse	Framatome	Under Review
98.	146	S14P-02180—02193 S14P-02214—02220	12/01 e-mails from A. Wise to A. Siemaszko re: OE13015, OE13003, 13056	INPO	Under Review
99.	147	S14P-02195—02197	Significant Event Notification # 220	INPO	Under Review
100.	149	S14P-02207—02212	INPO memorandum re: OE 13056	INPO	Under Review
101.	150	S14P-02222	11/30/01 e-mail from P. Goyal to A. Siemaszko re: CRDM Repair EWR 01-0462-00 costs	FENOC	Withhold in part

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
102.	151	S14P-02224—02284	04/09/01 e-mail from S. Fyitch to Industry re: attached final draft of subject safety assessment.	Framatome	Under Review
103.	152	S14P-02289—02292	INPO memorandum re: OE 13480	INPO	Under Review
104.	153	S14P-02373—02378	OE 13480	INPO	Under Review
105.	154	S14P-02380—02417	Framatome Engineering Information Record 5011603-01	Framatome	Under Review
106.	155	S14P-02419—02425	Significant Event Report 4-01	INPO	Under Review
107.	156	S14P-02428—02430	OE13919	INPO	Under Review
108.	160	S14P-02627—02632	09/11/01 letter from Framatome to FENOC re: Framatome proposal for Davis Besse RV head Lower Service Support Structure Access Openings Analysis -- #4160076)	Framatome	Under Review
109.	161	S14P—02807 S14P-03253—03254	Figure 8.6 Effect of Flange Clearances in Reducing Oxygen Levels at Bolts; Figure 8.7 effect of Boric Acid Deposits in Protecting Surface from Corrosion	EPRI	Under Review
110.	162	S14P-03167—03172	Framatome Tables re: Closure Stud Elongation Data	Framatome	Under Review
111.	163	S14P-03211—03243	Master-Lee Decon Services Instacote ML Brochure	Master Lee	Under Review
112.	166	S14P-03298—03345	B&WOG's Safety Assessment of Postulated Flaws for B&W Design Reactor Vessel Incore Monitoring Instrumentation Nozzles	Framatome	Under Review
113.	167	S14P-00002—00022	Draft GE Experience Report on Cracking in Alloy 182 (GENE B13-02080-00-03)	GE	Under Review
114.	168	S14P-00057—00062	OE 13454	INPO	Under Review
115.	169	S14P-00077—00079	Significant Event Notification 220	INPO	Under Review
116.	170	S14P-00562 S14P-02755	Figure 8-6: Effect of Flange Clearances in Reducing Oxygen levels at Bolts	EPRI	Under Review
117.	171	S14P-00564 S14P-02578 S14P-02646 S14P-02761	Framatome Enclosure 10.1 Service Structure Map	Framatome	Under Review
118.	172	S14P-00870—00873 S14P-01023—01031	OE 12980	INPO	Under Review
119.	173	S14P-01071—01077	Significant Event Report 4-01	INPO	Under Review
120.	174	S14P-01098	06/26/01 e-mail between FENOC employees re: Everest VIT Video Probe System, ROVVER System	FENOC	Withhold in part
121.	176	S14P-01710—01713	OE 13908	INPO	Under Review
122.	177	S14P-01718—01719 S14P-01723—01724	B&WOG RV Head Repair Bulletin	Framatome	Under Review
123.	178	S14P-01760—01788	Westinghouse Fleet Alloy 600 Work Shop—Reactor Vessel Head Penetration Issue	Westinghouse	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item ___)	Document Bates Label	Document Description	Owner	Status
124.	179	S14P-01831—01833	Excerpts from EPRI Handbook of Nuclear Materials (Dec. 1997)	EPRI	Under Review
125.	181	S14P-02625	Davis-Besse Engineering Work Request 01-03780-00	FENOC	Withhold in part
126.	182	S14P-02626—02635	09/21/01 FAX from M. McLaughlin to P. Goyal re: attached Framatome Proposal for Davis Besse RV Head Lower Service Support Structure Access Openings Analysis (FRA-ANP Proposal # 4160076)	FENOC	Withhold in part
127.	183	S14P-02790—02792	Framatome Seismic Tie-plate Drawings	Framatome	Under Review
128.	185	S14S-00237—00241	Davis-Besse RFO12 Commercial Summary	FENOC	Withhold in part
129.	186	S14S-00067	06/26/00 e-mail from G. Beam, Framatome, to A. Wilson re: Rev. 1 DB RFO12 Commercial Summary	FENOC	Withhold in part
130.	189	S16-00072—00078	Significant Event Notification 190	INPO	Under Review
131.	190	S17-00001—00055	B&W Report No. 51-1229638-1	Framatome	Under Review
132.	192	S21-00001—00011	Report of Investigation concerning Condition Report #2000-1037	FENOC	Withhold in part
133.	193	SUPP1-00001— 00199	FENOC contracts for 10-12RFO: Purchase Order and contract documentation	FENOC	Withhold entirely
134.	197	2S2-00973—00977 2S2-00986—00994 2S2-01822—01871	Calculation Package, #W-ENTP-11Q-309	Framatome	Under Review
135.	199	2S2-00995—01043 2S2-01193—01240	Calculation Package, #W-ENTP-11Q-308	Framatome	Under Review
136.	200	2S2-01044—01075	Several e-mail related to attached NRC Staff's Technical Assessment of VHP Nozzle Cracking	EPRI	Under Review
137.	201	2S2-01076—01083	Several e-mail related to attached NRC Technical Basis equations	EPRI	Under Review
138.	203	2S2-01127—01149 2S2-01241—01264	FENOC purchase order information	FENOC	Withhold in part
139.	204	2S2-01150—01151	FENOC Task Authorization re: SIA	FENOC	Withhold in part
140.	205	2S2-01270—01282	Framatome Technical Document, titled "Stress Report Summary for Reactor Vessel 33-1201205-02	Framatome	Under Review
141.	207	2S2-01286—01301 2S2-01307—01320	SIA Report No. SIR-01-095 (containing EPRI-licensed material)	EPRI	Under Review
142.	210	2S2-01689—01726	06/11/01 Letter from EPRI to MRP Alloy 600, 82/182 ITG with MRP-55 attached	EPRI	Under Review
143.	211	2S2-01727—01771	Calculation Package, #W-ENTP-11Q-307	Framatome	Under Review
144.	212	2S2-01872—01982	Calculation Package, #W-ENTP-11Q-320	Framatome	Under Review
145.	213	2S2-00001—00071 2S2-00079—00086	FENOC Purchase Orders & related purchase information	FENOC	Withhold entirely

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
146.	216	2S2-00142—00147 2S2-00261—00262	FENOC Task Authorizations	FENOC	Withhold in part
147.	220	2S2-00192—00230	Calculation Package, #W-ENTP-11Q-306	Framatome	Under Review
148.	228	2S2-01473—01571 2S2-01576—01639	EPRI Inspection Plan (PWR RPV Upper Head Penetrations)	EPRI	Under Review
149.	230	2S3-00235—00285	Documentation, including Service Agreements, purchase requisitions and procurement package information, re: Sargent & Lundy	FENOC	Withhold entirely
150.	232	2S3-00123—00124	FENOC Contractor Estimate for Engineering Services Task Authorization to Sargent & Lundy	FENOC	Withhold in part
151.	233	2S4-00001—00065	13RFO CRDM Nozzle Exam Report	Framatome	Under Review
152.	234	2S7-0019—00031	Davis-Besse CRDM Leadscrew Uncoupling/Coupling Parking & Replacement Procedure (marked "Controlled Copy"); contains Framatome information	Framatome	Under Review
153.	236	S14N-00889—00902	12/93 B&WOG's External Circumferential Crack Growth Analysis for B&W Design Reactor Vessel Head; BAW-10190P, Addendum 1	Framatome	Under Review
154.	237	S14N-00903—00940	12/97 B&WOG's Safety Evaluation for Control Rod Drive Mechanism Nozzle J-Groove Weld; BAW-10190P Addendum 2	Framatome	Under Review
155.	238	S14N-00047—00102	5/97 B&WOG's Safety Evaluation for B&W Design Reactor Vessel Head Control Rod Drive Mechanism Nozzle Cracking; BAW-10190P	Framatome	Under Review
156.	241	S14N-00276—00277	Undated B&WOG graphs assessing nozzle crack probabilities over time	Framatome	Under Review
157.	242	S14O-01522—01525	03/18/02 E-mail from INPO re: Small Accumulation of Boric Acid Found on Rx Vessel Head	INPO	Under Review
158.	243	S14O-00220—00227	05/18/01 E-mail from INPO re: Cracked Studs from Steam Generator Feedwater Flow Control Valves	INPO	Under Review
159.	245	S14O-00272—00277	05/18/01 e-mail from INPO re: Cracked studs from Steam Generator Feedwater Flow Control Valves	INPO	Under Review
160.	246	S14Q-02809—02845	10/08/01 SIA Calculation Package re: Finite Element Gap Analysis of CRDM Penetrations (Davis-Besse)	Framatome	Under Review
161.	247	S14Q-02873—02885	07/31/01 Letter from A. Marion (NEI) to B. Sheron (NRC-ONRR)	EPRI	Under Review
162.	248	S14Q-02888—02925	08/19/01 EPRI final draft response to NRC Bulletin 2001-01 (MRP-48)	EPRI	Under Review
163.	249	S14Q-02926—02982	4/30/02 Engineering Mechanics Corp. of Columbus, Failure Criterion Development and Parametric Finite Element Analysis to Assess Margins for Davis-Besse RPV Head Corrosion	Framatome	Under Review
164.	251	S14Q-06787—06802	11/4/01 Draft Recommended Crack Growth Rates for Evaluating Primary Water Stress Corrosion Cracking of Alloy 600 CRDM Nozzle Material (PWRMRP)	EPRI	Under Review
165.	252	S14Q-06803—06839 S14Q-07071—07107	8/19/01 PWRMRP Final Draft Response to NRC Bulletin 2001-01	EPRI	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
166.	253	S14Q-06840—06905 S14Q-06950—07017	5/01 PWRMRP Interim Alloy 600 Safety Assessments for US PWR Plants (MRP-44) Part 2: Reactor Vessel Top Head Penetrations	EPRI	Under Review
167.	254	S14Q-06906—06943	10/8/01 SIA Calculation Package re: Finite Element Gap Analysis of CRDM Penetrations (Davis-Besse)	Framatome	Under Review
168.	255	S14Q-06944—06949	7/31/01 MRP/EPRI Charts of key Plant Parameters for PWR Reactor Vessel Head Nozzle PWSCC Assessments	EPRI	Under Review
169.	256	S14Q-07018—07033	11/4/01 MRP Draft Recommended Crack Growth Rates for Evaluating PWSCC of Alloy 600 CRDM Nozzle Material (MRP-055)	EPRI	Under Review
170.	257	S14Q-07034—07046	Affidavits of J. Mallay (8/3/01) and R. Ganther (5/15/01), re: Framatome ANP proprietary documents, with attached copy of NRC Regulations	Framatome	Under Review
171.	258	S14Q-07047—07054	Unsigned and undated affidavit of S. Moffitt re: FENOC proprietary information, along with attachments on FENOC's classification policy	FENOC	Under Review
172.	259	S14Q-07055—07061	07/11/01 Meeting Minutes re: MRP Alloy 82/182 weld Integrity Issue, with attachments	EPRI	Under Review
173.	278	S14Q-07226—07252	12/20/01 E-mail from E. Szymanski to J. McGee re: 13RFO presentation, with attachment	FENOC	Withhold in part
174.	280	S14Q-07313—07316	10/23/01 E-mail from R. Cook to D. Wuokko re: TMI Event report from NRC through INPO	INPO	Withhold in part
175.	283	S14D-00001-00066	EPRI Report TP-1001491, Part 2	EPRI	Under Review
176.	284	S14D-00067-00105	EPRI Report 1006284	EPRI	Under Review
177.	285	S14D-00177-00265	Draft MRP response to NRC Bulletin 2001-01	EPRI	Under Review
178.	287	S14D-00268-00284	Draft MRP report regarding PWSCC growth rates in CRDM nozzles	EPRI	Under Review
179.	288	S14D-00306-00366	Draft MRP report regarding PWSCC growth rates in B&W Heats	EPRI	Under Review
180.	292	S14D-00539-00628	Draft MRP response to NRC Bulletin 2001-01	EPRI	Under Review
181.	293	S14D-00629-00794	Draft MRP response to NRC Bulletin 2001-01	EPRI	Under Review
182.	295	S14D-00975-01012	Draft MRP response to NRC Bulletin 2001-01	EPRI	Under Review
183.	297	S14D-01038-01050	NEI Letter RE; NRC Staff Question on EPRI Report TP-1001491	EPRI	Under Review
184.	298	S14D-01051-01111	MRP-48	EPRI	Under Review
185.	299	S14D-01521-01588	EPRI Report TP-10011491 Part 2	EPRI	Under Review
186.	300	S14D-01590-01629	06/07/01 letter from Duke Power to U.S. NRC re: request to use an alternative to ASME Boiler and Pressure Vessel Code (with Proprietary Framatome information included)	Framatome	Under Review
187.	301	S14D-01631-01670	MRP-48	EPRI	Under Review
188.	303	S14D-01675-01681	INPO OE 13056	INPO	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
189.	304	S14D-01682-01697	Framatome NRC Presentation	Framatome	Under Review
190.	305	S14D-01729-01823	Framatome Repair Presentation	Framatome	Under Review
191.	306	S14D-01824-01877	Draft MRP report regarding PWSCC growth rates in B&W Heats	EPRI	Under Review
192.	307	S14D-01878-01942	Framatome Repair process qualification	Framatome	Under Review
193.	308	S14D-01943-01961	Beaver Valley 1R14 inspection results	Framatome	Under Review
194.	309	S14D-01962-2001	EPRI Final Report 1006284.	EPRI	Under Review
195.	311	S14D-03476-3513	SIA Calculation	Framatome	Under Review
196.	312	S14D-03637-03639	Excerpts from EPRI NMAC Boric Acid Corrosion Guidebook.	EPRI	Under Review
197.	313	S14D-03640-03645	Excerpts from EPRI report TR-103354	EPRI	Under Review
198.	314	S14D-03879-03916	SIA Calculation	Framatome	Under Review
199.	315	S14D-03918-03955	SIA Calculation	Framatome	Under Review
200.	316	S14D-03957-03994	SIA Calculation	Framatome	Under Review
201.	317	S14D-04076-04142	Framatome CRDM Inspection	Framatome	Under Review
202.	319	S14D-04683-04722	SIA Calculation	Framatome	Under Review
203.	320	S14D-04770-04779	INPO SER 04-01	INPO	Under Review
204.	321	S14D-05372-05409	SIA Calculation	Framatome	Under Review
205.	327	S14D-06136-06173	SIA Calculation	Framatome	Under Review
206.	330	S14D-06348-06363	Draft template for 2001-01 response	Framatome	Under Review
207.	331	S14D-07049-07086	SIA Calculation	Framatome	Under Review
208.	335	S14D-07560-07600	SIA/FENOC calculation comments.	Framatome	Under Review
209.	336	S14D-07768-07778	LIS Meetings newsletter	Sciencetech	Under Review
210.	337	S14D-07885-07903	Dimensional data for CRDM interference fits	Framatome	Under Review
211.	344	S14J-02021-2037	Draft MRP report regarding PWSCC growth rates in CRDM nozzles	EPRI	Under Review
212.	346	S14J-2111-2115	E-mail dated 3/27/02 from J. Perez RE: CRDM Crack OE13480	INPO	Under Review
213.	347	S14J-02282-02319	SIA Calculation	Framatome	Under Review
214.	350	S14J-0015-0026	04/30/02 e-mail from J. Johnson to FENOC individuals re: attached OE13681	INPO	Under Review
215.	354	S14J-0312-0316	INPO event 38435 report	INPO	Under Review
216.	355	S14J-0325-0330	INPO event 38416 report	INPO	Under Review
217.	357	S14J-0416-0418	INPO OE 38416	INPO	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
218.	358	S14J-0421-0431	INPO OE 38416	INPO	Under Review
219.	359	S14J-0620-0623	INPO OE 12980	INPO	Under Review
220.	360	S14J-0638-0640	INPO OE 38493	INPO	Under Review
221.	361	S14J-0826-0831	LIS Newsletter	Sciencetech	Under Review
222.	362	S14J-0857-0859	LIS Newsletter	Sciencetech	Under Review
223.	363	S14J-00952-0960	E-mail forwarding OE 38383	INPO	Under Review
224.	365	S14J-1259-1290	LIS Newsletter, schedule	Sciencetech	Under Review
225.	366	S14J-1368-1379	INPO OE 13203	INPO	Under Review
226.	367	S14J-1381-1393	LIS Newsletter, schedule	Sciencetech	Under Review
227.	368	S14J-1433	INPO OE 38416	INPO	Under Review
228.	369	S14J-1434	INPO OE 38435	INPO	Under Review
229.	370	S14J-1435	INPO-OE 38493	INPO	Under Review
230.	372	S14J-1882-1890	LIS Newsletter, schedule	Sciencetech	Under Review
231.	373	S14M-06257-06267	Framatome CRDM UT Datasheets	Framatome	Under Review
232.	374	S14M-06269-06284	MRP report regarding PWSCC growth rates in B&W Heats	EPRI	Under Review
233.	375	S14M-6287	03/27/02 e-mail from D. Miller to EPRI re: NRC's use of proprietary information in EPRI Boric Acid Corrosion Guidebook	EPRI	Under Review
234.	376	S14M-06333-06348	Draft MRP-55 report regarding PWSCC growth rates in I600	EPRI	Under Review
235.	377	S14M-06350-06389	MRP-48 response to NRC Bulletin 2001-01, Report 1006284.	EPRI	Under Review
236.	378	S14M-06391-06494	MRP-44 Interim Report 1006284.	EPRI	Under Review
237.	379	S14M-06495-06510	Draft MRP-55 report regarding PWSCC growth rates in I600	EPRI	Under Review
238.	380	S14M-06511-06520	SIA Calculation	Framatome	Under Review
239.	381	S14M-06522-06566	MRP-48 response to NRC Bulletin 2001-01, Report 1006284.	EPRI	Under Review
240.	384	S14M-06663-06676	INPO OE13056	INPO	Under Review
241.	385	S14M-06678-06687	UT Inspection data	Framatome	Under Review
242.	386	S14M-06689-06691	INPO OE12466	INPO	Under Review
243.	387	S14M-06693-06696	E-mail from R. Slyker dated 7/16/01 forwarding INPO OE12466	INPO	Under Review
244.	388	S14M-06698-06761	SIA Calculations.	Framatome	Under Review
245.	389	S14M-06765-06767	E-mail forwarding INPO report regarding Oconnee 3 head leakage.	INPO	Under Review
246.	391	S14M-00999-01003	E-mail from R. Slyker dated 11/27/01 forwarding INPO OE12980	INPO	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
247.	392	S14M-01005-01008	INPO OE12980	INPO	Under Review
248.	394	S14M-01022-01033	E-mail from R. Slyker dated 11/27/01 forwarding INPO OE13480	INPO	Under Review
249.	396	S14M-01204-01209	E-mail from R. Slyker dated 3/20/02 forwarding INPO OE13447	INPO	Under Review
250.	397	S14M-01230	Framatome ANP drawing of BV-1 Rx Nozzle penetrations.	Framatome	Under Review
251.	398	S14M-01465-01481	E-mail from R. Slyker dated 3/11/02 forwarding INPO OE13377	INPO	Under Review
252.	399	S14M-01972-02004	SIA Calculation for response to 2001-01	Framatome	Under Review
253.	400	S14M-02057-02062	E-mail from R. Slyker dated 3/20/02 forwarding INPO OE13454	INPO	Under Review
254.	401	S14M-03765-03770	LIS Newsletter for week ending 11/9/01	Sciencetech	Under Review
255.	402	S14M-03913-03940	SIA Calculation for response to 1002-01	Framatome	Under Review
256.	403	S14M-04021	MRP data from EPRI for key plant parameters	EPRI	Under Review
257.	404	S14M-04071-04082	E-mail from R. Slyker dated 7/16/01 forwarding INPO OE12466	INPO	Under Review
258.	405	S14M-04348-04385	SIA Calculation for response to 2001-01	Framatome	Under Review
259.	406	S14M-04433-04470	SIA Calculation for response to 2001-01	Framatome	Under Review
260.	407	S14M-04772-04785	INPO SER 2-02	INPO	Under Review
261.	408	S14M-05697-05735	SIA Calculation for response to 2001-01	Framatome	Under Review
262.	411	S14R-00624-00654	Framatome UT Technique Assessment	Framatome	Under Review
263.	412	S14R-00662-00665	Budget information for DB head repairs	Framatome	Under Review
264.	413	S14R-00700	Budget information for DB head repairs	FENOC	Withhold in part
265.	416	S14R-00848-00885	SIA Calculation for response to 2001-01	Framatome	Under Review
266.	420	S14R-01632-01671	MRP-48 response to NRC Bulletin 2001-01, Report 1006284.	EPRI	Under Review
267.	422	S14R-01675-01724	Framatome proposal for DB inspection and repair services	Framatome	Under Review
268.	423	S14R-01778-1784	Framatome proposal 1231216 for inspection and repair service at DB	Framatome	Under Review
269.	424	S14R-01786-01801	Draft MRP-55 report regarding PWSCC growth rates in I600	EPRI	Under Review
270.	426	S14R-01815-01890	Interim assessment report to NRC from EPRI	EPRI	Under Review
271.	427	S14R-02916-2922	Framatome letter of intent for replacement vessel head	Framatome	Under Review
272.	428	S14R-02923-2930	FENOC internal project funding request for inspection of vessel heads	FENOC	Withhold in part
273.	429	S14R-02931	LIS Today E-mail	Sciencetech	Under Review
274.	430	S14R-02932-02933	08/27/01 e-mail from D. Lewis, Shaw Pittman LLP, regarding Rx cracks	Shaw Pittman	Under Review
275.	432	S14R-02935-03122	Draft EPRI papers and reports regarding RPV Head penetration cracking; MRP-48; MRP-55	EPRI	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
276.	434	S14R-03126-03202	MRP-44 interim Report 1006284 and comments	EPRI	Under Review
277.	435	S14R-03203-03211	Framatome site requirements document for CRDM repair at Crystal River 3	Framatome	Under Review
278.	436	S14R-03212-03225	Framatome CRDM Nozzle/Bore dimensional analysis	Framatome	Under Review
279.	437	S14R-03226-03288	Framatome CRDM Nozzle/Weld Safety Assessments	Framatome	Under Review
280.	438	S14R-03289-03334	Framatome Reactor Vessel Vent Inspection, Affidavit, and specification of Framatome Proprietary information contained in SIA Calculation.	Framatome	Under Review
281.	439	S14R-03335-03338	FENOC Budget information regarding CRDM engineering work.	FENOC	Withhold in part
282.	441	S14R-01082-01085	Non-disclosure agreement between Framatome, FENOC, and SIA	Framatome	Under Review
283.	442	S14R-01334-01340	INPO SER 4-01	INPO	Under Review
284.	443	S14R-01440-01477	SIA Calculation	Framatome	Under Review
285.	446	S14R-01917-01974	10/31/01 letter from Framatome to M. McLaughlin re: associated proposal reviews	FENOC	Withhold in part
286.	447	S14R-01975-01978	Trentec budgetary pricing for equipment hatch	Trentec	Under Review
287.	448	S14R-01979-01985	Financial analysis of head replacement timing options	FENOC	Withhold in part
288.	450	S14R-01991-02002	Framatome conceptual proposal for replacement vessel head.	Framatome	Under Review
289.	451	S14R-02092-2180	B&WOG Response to 97-01 Framatome Document 43-2301-00	Framatome	Under Review
290.	452	S14R-02181-02235	Framatome proposal for vessel head inspections	Framatome	Under Review
291.	453	S14R-02236-02244	FENOC Task authorization for PO 7076448 to Framatome	FENOC	Withhold in part
292.	455	S14R-02246-02251	FENOC Task authorization for PO 7076448 to Framatome	FENOC	Withhold in part
293.	456	S14R-02473	FENOC Task authorization for PO 7076448 to Framatome	FENOC	Withhold in part
294.	461	S14Q-00420-00433	LIS Meetings newsletter	Sciencetech	Under Review
295.	463	S14Q-00603-00667	MRP-44, #1006284.	EPRI	Under Review
296.	464	S14Q-01352-01367	Draft MRP-55 report regarding PWSCC growth rates in I600	EPRI	Under Review
297.	465	S14Q-01753-01756	MRP data from EPRI for key plant parameters	EPRI	Under Review
298.	466	S14Q-02041-02051 S14Q-02254-02264	LIS Meetings newsletter for week ending 11/9/01	Sciencetech	Under Review
299.	467	S14Q-02464-02470	INPO SER 4-01	INPO	Under Review
300.	468	S14Q-03332-03419	Davis-Besse Outage Cost Data	FENOC	Withhold in part
301.	469	S14Q-03495-03521	Davis-Besse Outage Budget Data	FENOC	Withhold in part
302.	470	S14Q-03965-03981	Davis-Besse 12RFO Outage Compensation materials	FENOC	Withhold in part
303.	471	S14Q-04240-04247	LIS Meetings newsletter for week ending 11/9/01	Sciencetech	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

<b>No.</b>	<b>File Name (Item __)</b>	<b>Document Bates Label</b>	<b>Document Description</b>	<b>Owner</b>	<b>Status</b>
304.	472	S14Q-04886-04923	SIA Calculation package	Framatome	Under Review
305.	474	S14Q-05058-05066	E-mail dated 11/30/01 RE: LIS Meetings and Schedule newsletter for week ending 11/30/01	Sciencetech	Under Review
306.	475	S14Q-05488-05490	INPO SEN 220	INPO	Under Review
307.	476	S14Q-05637-05640 S14Q-	MRP data from EPRI for key plant parameters	EPRI	Under Review
308.	477	S14Q-05688-05691	MRP data from EPRI for key plant parameters	EPRI	Under Review
309.	478	S14Q-05735-05742	INPO SER 04-01	INPO	Under Review
310.	479	S14Q-05865-05877 S14Q-06548-06555	LIS Meetings newsletter for week ending 11/21/01	Sciencetech	Under Review
311.	480	S14Q-05890-05911	LIS Meetings newsletter for week ending 11/09/01	Sciencetech	Under Review
312.	481	S14Q-06563-06570	LIS Meetings newsletter for week ending 08/10/01	Sciencetech	Under Review
313.	482	S14Q-06601-06611	INPO SER 04-01	INPO	Under Review
314.	483	S14Q-06620-06625	INPO OE 12466	INPO	Under Review
315.	484	S14Q-06638-06641	LIS Meetings newsletter for week ending 08/03/01	Sciencetech	Under Review
316.	485	S14Q-06649	Hand-annotated Page 15 of Draft MRP-55 report regarding PWSCC growth rates in I600	EPRI	Under Review
317.	486	S14Q-07325—07330 S14Q-07339—07350	RFO12 Davis-Besse Cost Information	FENOC	Withhold entirely

**Table 2: INDEX OF DOCUMENTS SUPPLIED TO NRC AIT FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name	Document Description	Owner	Status
318.	BAW 10190P (1400).pdf	BAW-1090P, "Safety Evaluation for B&W-Design Reactor Vessel Head Control Rod Drive Mechanism Cracking"	Framatome	Under Review
319.	BAW 10190P Addendum (1401).pdf	"Addendum to B&WOG Report BAW-1090P Entitled, 'External Circumferential Crack Growth Analysis for B&W-Design Reactor Vessel Head CRDM Nozzles,' dated December 1993"	Framatome	Under Review
320.	BOOK 1000975 (1412).pdf	"Boric Acid Guidebook, Revision 1 – Managing Boric Acid Corrosion Issues at PWR Power Stations"	EPRI	Under Review
321.	BOOK TR-102748 (1404).pdf	"Boric Acid Corrosion Guidebook – Recommended Guidance for Addressing Boric Acid Corrosion and Leakage Issues"	EPRI	Under Review
322.	PICTURE N-A (1407).pdf	Annotated photograph: "Davis-Besse CRDM Nozzle #3 – Characterization of Wastage Area Surrounding Nozzle Penetration."	Framatome	Under Review
323.	Serial 2735 (630).pdf	Serial 2735, "Supplemental Information in Response to NRC Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles"	Framatome	Under Review
324.	Serial 2741 (633).pdf	Serial 2741, "Responses to Requests for Additional Information Concerning NRC Bulletin 2001-01, 'Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles'"	Framatome	Under Review
325.	Serial 2747 (642).pdf	Serial 2747, "Supplemental Information in Response to the November 28, 2001 Meeting Regarding the Davis-Besse Nuclear Power Station Response to NRC Bulletin 2001-01"	Framatome	Under Review
326.	Serial 2761 (645).pdf	Serial 2761, "Reactor Pressure Vessel Head Penetration Examination Plans for the Davis-Besse Nuclear Power Station"	Framatome	Under Review
327.	TERMS A16892 (1232).pdf	BWOG Committee Meeting Materials	Framatome	Under Review
328.	BAW 2301 (1516).pdf	BAW-2301, "B&WOG Integrated Response to Generic Letter 97-01: 'Degradation of Control Rod Drive mechanism Nozzle and Other Vessel Closure Head Penetrations'"	Framatome	Under Review
329.	CHART n-a (1460).pdf	CRDM Nozzle Heats at B&W-Design Plants	Framatome	Under Review
330.	CHART n-a (1566).pdf	Plant PWSCC Ranking and Supporting Information	EPRI	Under Review
331.	MISC 03-501248A-01 (1645).pdf	CRDM Roll Expansion Procedure	Framatome	Under Review
332.	MISC N-A (1637).pdf	CRDM Roll Expansion Review Sheet	Framatome	Under Review
333.	Various — See Table 1 above	INPO OE Reports, SENS, SERs, SOERs	INPO	Under Review
334.	REPORT 51-1258525-00 (1546).pdf	B&WOG Report No. 51-1258525-00, "CRDM Nozzle Heat Treatment"	Framatome	Under Review
335.	RESUME N-A (1634).pdf	Resume for various FENOC personnel	FENOC	Withhold in part
336.	BOOK 2 (1890).pdf	At p. 20: BAW-2337P, "Safety Assessment of Postulated Flaws for B&W-Design Reactor Vessel Incore Monitoring Instrumentation Nozzles"	Framatome	Under Review

**Table 2: INDEX OF DOCUMENTS SUPPLIED TO NRC AIT FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

<b>No.</b>	<b>File Name</b>	<b>Document Description</b>	<b>Owner</b>	<b>Status</b>
337.	BOOK 8 (1741).pdf	At p. 46: B&WOG No. 51-5011603-1, "RV Head Nozzle and Weld Safety Assessment"	Framatome	Under Review
338.	Book 8 (1743).pdf	Framatome PowerPoint Meeting Presentation, "Alloy 600 Inspection and Repair	Framatome	Under Review
339.	MISC 51-5013435-02 (1886).pd	Framatome Engineering Record No. 51-5013435-02, "CRDM Nozzle/Bore Dimensional Analysis"	Framatome	Under Review
340.	SERIAL 2735 (1779).pdf	Serial 2735, "Supplemental Information in Response to NRC Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles"	Framatome	Under Review
341.	SERIAL 2741 (1796).pdf	Serial 2741, "Responses to Requests for Additional Information Concerning NRC Bulletin 2001-01, 'Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles'"	Framatome	Under Review

**Table 1: INDEX OF DOCUMENTS SUPPLIED TO NRC OI FOR WHICH PROPRIETARY TREATMENT MAY BE REQUESTED**

No.	File Name (Item __)	Document Bates Label	Document Description	Owner	Status
1.	1	3S1-00001—00051	11/07/02 position paper addressing role of FENOC individuals re: RPV head issue [contains unredacted adverse performance information]	FENOC	Withhold in part
2.	2	3S2-00001—00494	FENOC Execs/Managers' documents re: personnel actions; Human Resource records; summaries of individual performances; copies of disciplinary letters (redacted); matrixes identifying proposed actions to take against individuals	FENOC	Withhold in part
3.	3	2S5-0001—00016	Letters sent to sixteen FENOC employees which document FENOC's personnel actions relative to those individuals; these letters contain unredacted adverse performance information, and the individuals' names and addresses	FENOC	Withhold in part
4.	4	2S1-00001—00107	H. Bergendahl Personnel File [contains unredacted salary information, Social Security Number]	FENOC	Withhold entirely
5.	5	2S6-00001—00061	A. Siemaszko Personnel File containing unredacted adverse personnel information and individual's name, SSN, address, and salary information	FENOC	Withhold entirely
6.	6	S16-00014—00027 S16-00029—00033 S16-00057—00060 S16-00260—00297	Training on BACC and RPV Head nozzle integrity (bates range includes confidential personnel data such as SSN not redacted on attendance logs)	FENOC	Withhold in part
7.	7	S16-01078 S16-01120—01121	Training Workshop Completion records contain unredacted SSNs	FENOC	Withhold in part
8.	8	S10-00001—00229	Purchase Order regarding RPV Head Replacement and supporting documentation	FENOC	Withhold in part
9.	9	S10-00230—00420 2S3-00138—00234	FENOC purchase orders, procurement package, including FE presentation with cost calculations, and supporting documentation	FENOC	Withhold in part
10.	10	S10-00432—00454	Framatome Presentation, marked proprietary by Vendor	Framatome	Under Review
11.	11	S14A-00818—00856 S14H-10960—11072 S14H-00055—00185 S11-00100—00137 S14H-01671—01781	Serial 2735	Framatome	Under Review