

NRC FORM 591FF PART 1
 (11-2005)
 10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Framatome ANP, Inc. 2101 Horn Rapids Road Richland, WA 99352-0130	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region II, Division of Fuel Facilities Inspection 61 Forsyth Street, Suite 23T85 Atlanta, GA 30303	
REPORT 70-1257/2005-005		
3. DOCKET NUMBER(S) 70-1257	4. LICENSEE NUMBER(S) SNM-1227	5. DATE(S) OF INSPECTION 11/28 -12/2 and 12/5 - 12/9/ (2005)

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed. See list of items opened and closed on NRC Form 591FF Part 3.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion were satisfied.

1 Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

10 CFR 71.5 (a)(vi) requires the licensee to provide hazardous materials employee(hazmat) training as outlined in 49 CFR 172.704. Specifically, in-depth security training for hazmat employees should have been implemented by December 22, 2003. In addition, the licensee's site specific procedure, E09-01-002, required in-depth security training to supplement the existing hazmat employee training program. Contrary to the above, on December 5, 2005, the licensee discovered through an internal audit that in-depth security training had never been implemented. This non repetitive, licensee-identified and corrected violation is being treated as a non-cited violation (NCV), consistent with Section VI.A.8 of the NRC Enforcement Policy (NCV 70-1257/2005-05-05), Failure to provide In-Depth Security Training. Corrective actions included entering the finding into the corrective action program, and implementing the training into the next hazmat employee training session.

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Not Applicable		
NRC INSPECTOR	Cynthia Taylor		1/6/05

Distribution w/encls:

J. Pelchat, RII
B. Gleaves, NMSS
N. Baker, NMSS
Public

PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE NON-SENSITIVE
ADAMS: Yes ACCESSION NUMBER: _____

OFFICE	RII:DFFI	RII:DFFI	RII:DFFI				
SIGNATURE							
NAME	R. Gibson	J. Jimenez	C. Taylor				
DATE	1/ /2006	1/ /2006	1/ /2006	1/ /2006	1/ /2006	1/ /2006	1/ /2006
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY DOCUMENT NAME: E:\Filenet\ML060200484.wpd