

ATTACHMENT 1

Region IV Table 1 DNMS LICENSEE EVENT REPORTS--OPENED DECEMBER 2005							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
12/12/05	12/12/05	12/12/05	Pathfinder Energy Services, Inc.	17-27623-01	10 CFR 39.77 (c) and (d)	Irretrievable well logging sources: Offshore, Gulf of Mexico, Federal Waters; Eugene Island Block	Open

Region IV Table 2 DNMS LICENSEE EVENT REPORTS Previously Received and Still Under Review Current for DECEMBER 2005							
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
02/23/05	08/12/04	05/13/05	Southern California Edison SONGS, Unit 1	DPR-13	License Controlled Specification Surveillance Requirement 3.7.107.3	Amount of removable contamination on a leak test sample of a plutonium-beryllium neutron source exceeded reporting limits.	Open
07/14/05	07/14/05	07/15/05	Global X-Ray & Testing Corporation	LA-0577-L01	10 CFR 34.101(a)(2)	During radiographic operations on pipe lay barge, a source assembly did not retract to its fully shielded and secure position. RSO was dispatched to the remote site and recovered the source.	Open

Region IV Table 2

**DNMS LICENSEE EVENT REPORTS**  
**Previously Received and Still Under Review**  
**Current for DECEMBER 2005**

REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
07/19/05	01/06/05	07/19/05	Rapid City Regional Hospital	40-00238-04	10 CFR 30.50	High Dose Rate Brachytherapy Remote Afterloader device alarmed, indicating a problem with source positioning and locked the source in what was determined to be its safe shielded position.	Open
08/05/05	07/02/05	08/02/05	Department of Energy, Idaho Operations Office Fort St. Vrain Independent Spent Fuel Storage Installation	SNM-2504	Technical Specification 5.6.2	Violation of admin. Control - Testing of communications equip. was implemented less frequently than described in the Physical Protection plan.	Open
08/12/05	06/14/05	09/01/05	Pacific Gas and Electric Company Humboldt Bay Power Plant, unit 3	DPR-7	10 CFR 50.73(a)(2) and 10 CFR 73.(a)(4)	Tsunami warning at facility required evacuation of all licensee personnel.	Open
09/09/05	08/11/05	09/13/05	Pathfinder Energy Services, Inc.	17-27623-01	10 CFR 39.77 (c) and (d)	Irretrievable well logging sources: Offshore LA, Gulf of Mexico, Federal Waters; Linder Oil Co; West Cameron Block 168; OCS-G 5283 #4; API 17-700-41229-00	Open
10/01/05	09/30/05	10/04/05	Department of the Army White Sands Missile Range, NM	30-02405-10	10 CFR 30.50(b)	Panoramic irradiator source stuck in unshielded position	Open
11/09/05	09/23/05	11/09/05	Halliburton Energy Services, Inc.	N/A	10 CFR 31.5(b)(10) 10 CFR 20.2201	Loss of two generally licensed devices located on a drilling rig in the Gulf of Mexico (a result of Hurricane Rita).	Open

Region IV		Table 2		DNMS LICENSEE EVENT REPORTS Previously Received and Still Under Review Current for DECEMBER 2005			
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
11/21/05	09/06/05	11/21/05	Department of the Air Force	42-23439-01AF	10 CFR 20.2201(a)	Loss of an Ion Track Vapor Tracer containing a 10 mCi nickel-63 source.	Open

~ Agreement State Licensee working under the reciprocity provisions of 10 CFR 150.20.

Region IV		Table 3		DNMS LICENSEE EVENT REPORTS--CLOSED DECEMBER 2005 (See attached Licensee Event Report Evaluation Form)			
REPORT DATE	EVENT DATE	DATE REC'D	LICENSEE	LICENSE NUMBER	REPORTING REQUIREMENT	DESCRIPTION	STATUS
07/04/05 ~ ~	07/07/05	07/04/05	Baker Hughes Oilfield Operations, Inc. dba Baker Hughes INTEQ	17-27437-01	10 CFR 39.77(c) and (d)	Irretrievable well logging sources: Offshore LA, Gulf of Mexico, Federal Waters; Chevron Texaco; Rig Hercules 21; Main Pass Block 40; OCS-G 0373 BF010	Closed

~ ~ Event inadvertently left out of reports for July 2005 through October 2005.