

FPL Energy Seabrook Station P.O. Box 300 Seabrook, NH 03874 (603) 773-7000

January 23, 2006

Docket No. 50-443 SBK-L- 06014

U.S. Nuclear Regulatory Commission Attn.: Document Control Desk Washington, DC 20555-0001

Seabrook Station
2005 Annual Report of Removable
Contamination from Sealed Source or Fission Detector

In accordance with Technical Specification 3.7.8, "Sealed Source Contamination," FPL Energy Seabrook, LLC hereby reports that during 2005, there were no leaking sources.

Should you have any questions, please contact Mr. Ronald M. Thurlow, Acting Health Physics Department Manager, at (603) 773-7438.

Very truly yours,

FPL Energy Seabrook, LLC

Gene St. Pierre Site Vice President

reactions are a control of the control of the control of the control of the professional and an expension of the control of th

cc: S. J. Collins, NRC Region I Administrator

G. E. Miller, NRC Project Manager

as the space of the Political Control

G. T. Dentel, NRC Resident Inspector