VIDOLLEU WITCH 4.1 DUNTOUNIHAHOR ID DEGINIUNEL DOCUMENT TRANSIC TED HEREWITH CONTAINS 10 CFR 7 30 INFORMATION

Mr. R. W. Sharkey

January 19, 1999

Director; Regulatory Affairs ABB CENO Fuel Operations Combustion Engineering, Inc. 3300 State Road P Hematite, MO 63047

SUBJECT: INSPECTION NO. 70-36/98-204 AND NOTICE OF VIOLATOIN

Dear Mr. Sharkey

The Nuclear Regulatory Commission (NRC) conducted a routine inspection of your facility's material control and accounting (MC&A) safeguards program on December 7 - 11, 1998. The enclosed report presents the results of that inspection.

The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations of activities in progress. At the conclusion of the inspection, the findings were discussed with you and members of your staff.

Based upon the results of the inspection, the NRC has determined that a violation of NRC requirements occurred. The violation is cited in the enclosed Notice of Violation (Notice), and the circumstances surrounding the violation are described in detail in the enclosed report. This violation is of concern to the NRC because current knowledge of items status/location must be maintained to ensure the safeguards risk of material loss, theft, or diversion is adequately addressed.

Under the provisions of Section 2.790(d), reports containing information related to a licensee's MC&A program are exempt from public disclosure. Accordingly, Enclosure 2 will not be placed in the Public Document Room.

Should you have any questions concerning this letter, please contact me.

Sincerely,

Philip Ting, Chief Original signed by Philip Ting

Act, exempti

Operations Branch

Division of Fuel Cycle Safety Information in this record was deleted in accordance with the Freeton of Information and Safeguards, NMSS

Docket No. 70-0036 License No. SNM-33

cc w/enclosure: Dr. Bruce Kaiser, Vice President

Fuel Operations, ABB CENO

R. A. Kucera, Director

Missouri Department of Natural Resources

DISTRIBUTION:

CEmeigh, FCLB

MMessier, T9E10 (w/o encls)

Docket File 70-36 SSoong, FCLB

PDR, LPDR (w/o encls)

NMSS r/f

WSmith FCOB

FCSS r/f

FCOB r/f MRodgers, PMDA (w/o encis)

JOlencz FCOB TPham, FCLB

Case File

PHiland, RIII DOCUMENT NAME: (ABB Disk) abb98204.wpd

OFC	FCOB	E.	E€0B	E	FCOB	Ε	FC0B	E	FC0B		FCOB	E
"ME	PHarich		CCollins ac		LHarrisky		DOMhaley		WTroskoski		Pring	
, TE	1/14/99	7	1 /14/99		1 /14 /99		1 / /4/99		11/199		1/19/99	

C=COPY = COVER & ENCLOSURE N = NO COPYFFICIAL RECORD COPY

HEN 27290-INFORMATION IS REMOVED

Chang her por

900 Plan

DECONTRO! LED WHEN 4.190 INFURMATION IS KENIUVED DOCUMENT TRANSIN ED HEREWITH CONTAINS 10 CFR 90 INFORMATION



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001 January 19, 1999

Mr. R. W. Sharkey Director, Regulatory Affairs ABB CENO Fuel Operations Combustion Engineering, Inc. 3300 State Road P Hematite, MO 63047

SUBJECT: INSPECTION NO. 70-36/98-204 AND NOTICE OF VIOLATION

Dear Mr. Sharkey:

The Nuclear Regulatory Commission (NRC) conducted a routine inspection of your facility's material control and accounting (MC&A) safeguards program on December 7 - 11, 1998. The enclosed report presents the results of that inspection.

The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations of activities in progress. At the conclusion of the inspection, the findings were discussed with you and members of your staff.

Based upon the results of the inspection, the NRC has determined that a violation of NRC requirements occurred. The violation is cited in the enclosed Notice of Violation (Notice), and the circumstances surrounding the violation are described in detail in the enclosed report. This violation is of concern to the NRC because current knowledge of items status/location must be maintained to ensure the safeguards risk of material loss, theft, or diversion is adequately addressed.

Under the provisions of Section 2.790(d), reports containing information related to a licensee's MC&A program are exempt from public disclosure. Accordingly, Enclosure 2 will not be placed in the Public Document Room.

Should you have any questions concerning this letter, please contact me.

Sincerely,

Philip Ting, Chief

Operations Branch

Division of Fuel Cycle Safety and Safeguards, NMSS

Docket No. 70-0036 License No. SNM-33

cc w/enclosure: Dr. Bruce Kaiser, Vice President

Fuel Operations, ABB CENO

R. A. Kucera, Director

Missouri Department of Natural Resources

DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED

DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED DOCUMENT TRANSMITTED HEREWITH CONTAINS 10 CFR 2.790 INFORMATION

NOTICE OF VIOLATION INSPECTION NO. 70-36/98-204

ABB Combustion Engineering, Inc. Hematite, Missouri 63047

Docket No. 70-36 License No. SNM-33

During a Nuclear Regulatory Commission (NRC) inspection conducted on December 7 - 11, 1998, a violation of NRC requirements was identified. In accordance with the "General Statements of Policy and Procedure for NRC Enforcement Actions," NUREG-1600, the violation is described below.

VIOLATION NO. 98-204-01

10 CFR 74.31 (c) (6) states in part:

"The licensee shall maintain current knowledge of items when the sum of the time of existence of an item, the time to make a record of the item, and the time necessary to locate the item exceeds 14 days."


Contrary to the above, the licensee failed to maintain current knowledge of items in that eight fuel bundles were shipped on November 18, 1998, but the item control data base was not updated until December 8, 1998. During this time interval, which exceeds 14 days, the licensee had not maintained a current knowledge of the eight fuel bundles.

This is a severity level IV violation (Supplement III).

Pursuant to the provisions of 10 CFR 2.201, ABB Combustion Engineering is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with copies to the Regional Administrator, Region III, and Chief, Fuel Cycle Operations Branch, Division of Fuel Cycle Safety and Safeguards, NMSS, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps taken to avoid any further violations, and (4) the date when full compliance will be achieved.

Enclosure 1

DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED
DOCUMENT TRANSMITTED HEREWITH CONTAINS 10 CFR 2.790 INFORMATION



DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED DOCUMENT TRANSMITTED HEREWITH CONTAINS 10 CFR 2.790 INFORMATION

-2-

Your response may reference or include previously docketed correspondence if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or Demand for Information may be issued as to why the license should not be modified, suspended or revoked, or why such other actions as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because your response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. If personal privacy or proprietary information is necessary to provide an acceptable response, then please provide a bracketed copy of your response that identifies the information that should be protected, and a redacted copy of your response that deletes such information. If you request withholding of such material, you must specifically identify portions of your response that you seek to have withheld and provide in detail the bases for your claim of withholding (e.g., explain why the disclosure of information will create an unwarranted invasion of personal privacy or provide the information required by 10 CFR 2.790(b) to support a request for withholding confidential commercial or financial information). If safeguards information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21.

Dated at Rockville, Maryland this 19th day of January 1999

DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED DOCUMENT TRANSMITTED HEREWITH CONTAINS 10 CFR 2.790 INFORMATION

DECONTROLLED WHEN 2.790 INFORMATION IS REMOVED DOCUMENT TRANSMITTED HEREWITH CONTAINS 16 CFR 2.790 INFORMATION

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF NUCLEAR MATERIAL SAFETY AND SAFEGUARDS

Docket No.:

70-36

License No.:

SNM-33

Report No.:

70-36/98-204

Safeguards Group:

III

Licensee:

ABB Combustion Engineering, Inc.

Fuel Operations Manufacturing Facility

Location:

Hematite, MO

Dates:

December 7-11, 1998

Inspectors:

C. Collins, MC&A Physical Scientist, Inspection Section L. Harris, MC&A Physical Scientist, Inspection Section D. Whaley, MC&A Physical Scientist, Inspection Section

Approved by:

P. Ting, Chief Operations Branch

Division of Fuel Cycle Safety and Safeguards, NMSS

Enclosure 2

DECONTROLLED WHEN 2,790 INFORMATION REMOVED DOCUMENT TRANSMITTED HEREWITH CONTAINS 10 CFR 2.790 INFORMATION

