



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**

REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, ILLINOIS 60532-4352

February 28, 2006

Ms. Denise L'Allier-Pray  
Radiation Safety Officer  
Eastman Kodak Co.  
1 Imation Place-3A  
Oakdale, MN 55128

**SUBJECT: TELEPHONE INTERVIEW TO EVALUATE THE RADIATION SAFETY  
PROGRAM**

Dear Ms. L'Allier-Pray:

This refers to the interview by telephone on February 24, 2006. The interview was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the U.S. Nuclear Regulatory Commission rules and regulations and with the conditions of your license. No regulatory concerns were identified.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If you have any questions about this matter, please contact me at (630) 829-9861, or at my email address [tsg2@NRC.gov](mailto:tsg2@NRC.gov).

Sincerely,

A handwritten signature in cursive script, appearing to read "Tony Go".

Tony Go, Health Physicist  
Materials Inspection Branch

License No.: 22-32610-01  
Docket No.: 030-37114

February 28, 2006

Ms. Denise L'Allier-Pray  
Radiation Safety Officer  
Eastman Kodak Co.  
1 Imation Place-3A  
Oakdale, MN 55128

SUBJECT: TELEPHONE INTERVIEW TO EVALUATE THE RADIATION SAFETY PROGRAM

Dear Ms. L'Allier-Pray:

This refers to the interview by telephone on February 24, 2006. The interview was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the U.S. Nuclear Regulatory Commission rules and regulations and with the conditions of your license. No regulatory concerns were identified.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If you have any questions about this matter, please contact me at (630) 829-9861, or at my email address [tsg2@NRC.gov](mailto:tsg2@NRC.gov).

Sincerely,

/RA/

Tony Go, Health Physicist  
Materials Inspection Branch

License No.: 22-32610-01  
Docket No.: 030-37114

Distribution:  
Docket File  
Carole Ariano

DOCUMENT NAME:G:\SEC\IR Materials Insp\Eastman Kodak tel inspection.fn.wpd

X Publicly Available       Non-Publicly Available       Sensitive      X Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

|        |          |  |          |  |      |  |      |  |
|--------|----------|--|----------|--|------|--|------|--|
| OFFICE | RIII     |  | RIII     |  | RIII |  | RIII |  |
| NAME   | Go:mb    |  | Madera   |  |      |  |      |  |
| DATE   | 02/28/06 |  | 02/28/06 |  |      |  |      |  |

OFFICIAL RECORD COPY



| QUESTIONS   | ANSWERS   |
|---|---|
| <p>6. Describe leak testing of the sealed source(s). How often and who analyzed the leak test samples? What were the most recent results?</p>   | <p>The last leaktest results of these two devices did not indicate leakage. The last leaktest was performed in December 2005. The licensee performed leaktest every six months.</p> |
| <p>7. Describe physical inventory of all byproduct material and NMMSS-reportable materials in your possession. When was the last inventory completed? Were all the sources located?</p> | <p>The licensee did not possess NMMSS reportable materials at this time. The inventory of these two devices was performed every six-month.</p>                                      |
| <p>8. Describe your provisions for repair and maintenance of your device or source holder.</p>  | <p>Repair and maintenance were performed by the manufacturers (HP and 3M).</p>  |
| <p>9. Describe any unusual events involving the byproduct material or the device(s) in which it is used (i.e., fire, explosion, natural disaster.)</p>                                  | <p>There were no unusual events involving these licensed devices such as fire and explosion.</p>  |