NRC FORM 591M PAR (10-2003) 10 CFR 2.201		PECTION REPORT AN		S. NUCLEAR REGULATO SPECTION	RY COMMISSION
LICENSEE/LOCATION INSPECTED: CertainTeed Corporation 1220 Oak Hill Road Mountaintop, PA 18707			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)			NC
030-17473		37-11020-02		February 15, 2006	
Nuclear Regulatory Comrof procedures and repres X 1. Based on th 2. Previous vio 3. The violatior identified, non-resident common comm	mission (NRC) rules and rentative records, interview e inspection findings, no valution(s) closed. (s), specifically described	I to you by the inspector as no ction was or is being taken, ar	of your license. The inspect thing by the inspector. The inspector is the inspector of the inspector. The inspector is the inspector of the in	ion consisted of selective exinspection findings are as following are as following cited because they were	xaminations ollows: e self-
		activities, as described below a			and are
	Licensee's	Statement of Correcti	ve Actions for Item 4	l, above.	
corrective actions is made	30 days, the actions desc e in accordance with the r e will be achieved). I unde	ribed by me to the inspector vequirements of 10 CFR 2.201 rstand that no further written reted Name	vill be taken to correct the viol (corrective steps already takesponse to NRC will be requi	lations identified. This state en, corrective steps which	will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Orvsia Masnyk Ba	allev	/R	A/	02-15-2006