

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Macalaster College REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 070-00634	4. LICENSE NUMBER(S) SNM-573	5. DATE(S) OF INSPECTION 2/24/06	
6. INSPECTION PROCEDURES USED TI 2800-035	7. INSPECTION FOCUS AREAS 2800/035-01 through 10.04		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 22120	2. PRIORITY K5	3. LICENSEE CONTACT Heather McCollor - RSO	4. TELEPHONE NUMBER 651-696-6484
------------------------------------	--------------------------	--	--

<input checked="" type="checkbox"/> Main Office Inspection <input type="checkbox"/> Field <input type="checkbox"/> Temporary Job Site	Next Inspection Date: <u>NA - Special Inspection</u>
---	--

PROGRAM SCOPE

The scope of this inspection was limited to the procedures described in Temporary Instruction 2800-035. The licensee is authorized under its NRC license to possess and use the subject material for research and development and student instruction. During this special inspection the NRC inspector determined that the subject material is not on permanent loan from the U.S. Department of Energy (DOE).

Performance Observations

During this special inspection the inspector observed the licensed facility and conducted a physical inventory of the subject material. All sources were accounted. The scope of this inspection was limited to the procedures described in Temporary Instruction 2800-035. The licensee is authorized under its NRC license to possess and use the subject material for research and development and student instruction. The inspector noted a discrepancy between NRC documentation and licensee physical inventory. The discrepancy is not related to security of subject material and the licensee will correct the discrepancy as soon as possible.