

NRC FORM 591M PART 1
 (10-2003)
 10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Stavola Asphalt Company P.O. Box 482 Red Bank, New Jersey 07701		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2006-001			
3. DOCKET NUMBER(S) 030-33853	4. LICENSE NUMBER(S) 29-20760-02	5. DATE(S) OF INSPECTION February 17, 2006	

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1500, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 30.34 (i) requires that each portable gauge licensee shall use a minimum of two independent physical controls that form tangible barriers to secure portable gauges from unauthorized removal, whenever portable gauges are not under the control and constant surveillance of the licensee.

Contrary to the above, on February 17, 2006, the licensee did not use a minimum of two independent physical controls that form tangible barriers to secure three portable gauges from unauthorized removal. Specifically, the licensee routinely stores portable gauges in a storage area locked with one lock. The storage area is located in a building which is not locked at all times and is used as a common area for employees who may not be authorized users of the gauges. The licensee also transports the portable gauges in company owned open bed pick up trucks. The licensee described how they secure the gauges in the vehicles in order to comply with 10 CFR 30.34.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Edward E. Acquaro		2-21-06
NRC INSPECTOR	Judith A. Joustra		2/17/06