

**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE

**Stavola Asphalt Company  
P.O. Box 482  
Red Bank, New Jersey 07701**

REPORT  
NUMBER(S)                      2006-001

2. NRC/REGIONAL OFFICE

**U.S. Nuclear Regulatory Commission  
Region I, 475 Allendale Road  
King of Prussia, Pennsylvania 19406-1415**

3. DOCKET NUMBER(S)

030-33853

4. LICENSE NUMBER(S)

29-20760-02

5. DATE(S) OF INSPECTION

February 17, 2006

(Continued)

The licensee's method as described by the licensee does not appear to comply with 10 CFR 30.34. Specifically, the licensee places two locks directly on the shipping container to prevent someone from removing the gauge from the shipping container, and locks a single chain to an eye bolt on the lid of the shipping container and attaches the chain to the vehicle. This configuration establishes only a single barrier that must be defeated in order to remove the transportation case with the gauge in it.

The licensee stated that they will establish a second barrier to be used during on site storage area and during transport.