

RECEIVED  
REGION 1

2006 FEB 27 PM 1:40

Sentara CarePlex Hospital  
3000 Coliseum Drive  
Hampton, Virginia 23666  
www.sentara.com

February 14, 2006

U.S. Nuclear Regulatory Commission  
Region I Office, Division of NMSS  
Attn: Materials Licensing  
475 Allendale Road  
King of Prussia, PA 19406

NMSB1

03003331

To whom it may concern, regarding license number 45-09087-01:

We would like to add spaces in our hospital for prostate seed implants procedures. Iodine-125 seeds are now being inserted in OR 5 and OR 10 in the second floor Main Operating Room, which are surveyed after each use. See the attached plans for details of these locations, which are marked with an asterisk.

Also please add these authorized medical physicists as listed on license 45-00131-02:

Gwendolyn King, Alexander Gray and Timothy Kennelly.

Please remove all 31.11 authorization for laboratory use from our license. I-125 was last used in 1996 in the previous Sentara Hampton General Hospital facility, which was vacated in 2002 and demolished in 2003. No surveys were done in the lab spaces, although approximately 40 half-lives had passed at that time. No use of isotopes under 31.11 has taken place in our new facility, which was licensed in 2002.

These changes have been reviewed and approved by our Radiation Safety Committee. For more information, please do not hesitate to contact our Radiation Safety Officer, Sandy Wolff, at (757) 388-3030 or page her at (888) 341-5703.




Sincerely,

Tamika Jefferson  
Director, Facilities and Patient Care Services  
Sentara Careplex Hospital

138499

NMSS/REG I MATERIALS-002

SENTARA CAREPLEX HOSPITAL  
 Main Operating Room  
 Second Floor



This is to acknowledge the receipt of your letter/application dated

2/14/2006, and to inform you that the initial processing which includes an administrative review has been performed.

AMEND. 45-09037-01  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 138499.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.