

March 22, 2006

Mr. Christopher M. Crane  
President and Chief Nuclear Officer  
Exelon Nuclear  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

SUBJECT: ERRATA TO DRESDEN NUCLEAR POWER STATION, UNITS 2 AND 3  
NRC PROBLEM IDENTIFICATION AND RESOLUTION INSPECTION  
REPORT 05000237/2006002; 05000249/2006002

Dear Mr. Crane:

On March 9, 2006, the U.S. Nuclear Regulatory Commission (NRC) issued problem identification and resolution Inspection Report 05000237/2006002; 05000249/2006002 (ML060680422) for your Dresden Nuclear Power Station, Units 2 and 3. The list of items opened and closed during the inspection is incomplete in the original report. The enclosed errata contains the complete listing, and should be inserted where appropriate into problem identification and resolution Inspection Report 05000237/2006002; 05000249/2006002.

We apologize for any inconvenience to you and your staff.

Sincerely,

/RA/

Mark A. Ring, Chief  
Branch 1  
Division of Reactor Projects

Docket Nos. 50-237; 50-249  
License Nos. DPR-19; DPR-25

Enclosure: Errata to Inspection Report No. 05000237/2006002;  
05000249/2006002

See Attached Distribution

DOCUMENT NAME:E:\Filenet\ML060830065.wpd

☐ Publicly Available

☐ Non-Publicly Available

☐ Sensitive

☐ Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII				
NAME	ABarker: dtp		MRing				
DATE	03/22/2006		03/22/2006				

**OFFICIAL RECORD COPY**

C. Crane

-2-

cc w/encl:     Site Vice President - Dresden Nuclear Power Station  
                  Dresden Nuclear Power Station Plant Manager  
                  Regulatory Assurance Manager - Dresden  
                  Chief Operating Officer  
                  Senior Vice President - Nuclear Services  
                  Senior Vice President - Mid-West Regional  
                      Operating Group  
                  Vice President - Mid-West Operations Support  
                  Vice President - Licensing and Regulatory Affairs  
                  Director Licensing - Mid-West Regional  
                      Operating Group  
                  Manager Licensing - Dresden and Quad Cities  
                  Senior Counsel, Nuclear, Mid-West Regional  
                      Operating Group  
                  Document Control Desk - Licensing  
                  Assistant Attorney General  
                  Illinois Emergency Management Agency  
                  State Liaison Officer  
                  Chairman, Illinois Commerce Commission

ADAMS Distribution:

GYS

MXB

RidsNrrDirslrib

GEG

KGO

DRC1

CAA1

C. Pederson, DRS (hard copy - IR's only)

DRPIII

DRSIII

PLB1

JRK1

[ROPreports@nrc.gov](mailto:ROPreports@nrc.gov) (inspection reports, final SDP letters, any letter with an IR number)

ERRATA TO NRC PROBLEM IDENTIFICATION AND RESOLUTION INSPECTION  
REPORT 05000237/2006002; 05000249/2006002

1. On Page 1 of the attachment under the heading of “ITEMS OPENED, CLOSED, AND DISCUSSED” insert the following:

**ITEMS OPENED, CLOSED, AND DISCUSSED**

Items Opened

05000237/2006002-01 05000249/2006002-01	FIN	Failure to enter ERV discrepancies into CAP.
05000237/2006002-02 05000249/2006002-02	NCV	Failure to identify an inadequate surveillance test procedure.
05000237/2006002-03 05000249/2006002-03	URI	Adequacy of licensee’s practice of not performing as-found testing of the ERVs.

Items Closed

05000237/2006002-01 05000249/2006002-01	FIN	Failure to enter ERV discrepancies into CAP.
05000237/2006002-02 05000249/2006002-02	NCV	Failure to identify an inadequate surveillance test procedure.

Items Discussed

None

Enclosure

Enclosure