



PATHFINDER

February 27, 2006

Mr. William Von Till
Chief, Uranium Processing Section
Fuel Cycle Facilities Branch
Division of Fuel Cycle Safety and Safeguards
Office of Nuclear Material Safety and Safeguards
U.S. Nuclear Regulatory Commission
11545 Rockville Pike
Rockville, Maryland 20852-2738

Re: Docket No. 40-2259, License No. SUA-672

Dear Mr. Von Till:

Condition 22 of the referenced license requires the submittal of the results of effluent and environmental monitoring in accordance with 10 CFR 40.65. This is to advise you that no effluent or environmental monitoring was done during the third and fourth quarters of 2005 at the Lucky Mc tailings site, consistent with amendment number 64 to the license. The ground water monitoring results for the third and fourth quarters, 2005, were submitted to the NRC on January 27, 2006 in a separate report pursuant to condition 60 of the license.

Sincerely,

T. W. Hardgrove
Manager, Reclamation Operations

cc: J. Whitten, U.S. NRC – Region IV
D. L. Wichers