


- NOTES:**
1. THE DEPTH AND THICKNESS OF SOIL AND ROCK STRATA INDICATED ON THE SUBSURFACE SECTION WAS OBTAINED BY INTERPOLATING BETWEEN BORINGS EXCEPT IN THE AREAS WHERE EXCAVATION MAPPING DATA WAS ADDED. INFORMATION ON ACTUAL SOIL AND ROCK CONDITIONS EXISTS ONLY AT BORING LOCATIONS AND PLANT EXCAVATIONS. IT IS POSSIBLE THAT SOIL AND ROCK CONDITIONS BETWEEN BORINGS MAY VARY FROM THOSE INDICATED.
 2. THE DISCUSSION IN THE TEXT IS NECESSARY FOR PROPER UNDERSTANDING OF THE NATURE OF SUBSURFACE MATERIALS.
 3. ELEVATIONS REFER TO U.S.G.S. DATUM.
 4. LOCATION OF GEOLOGIC SECTION H-H' IS SHOWN ON FIGURE 2.5-16, SHEET 3.
 5. THE PARKLAND SAND IS NOT DIFFERENTIATED FROM THE EQUALITY FORMATION IN THIS GEOLOGIC SECTION.



**BRAIDWOOD STATION
UPDATED FINAL SAFETY ANALYSIS REPORT**

**FIGURE 2.5-25
GEOLOGIC SECTION H-H'**

**INFORMATION
ONLY**

0-3