

From: "Croulet, Donald" <dcroule@entergy.com>
To: "Conroy, Pat" <PConroy@entergy.com>, "Cox, Mark R" <mcox90@entergy.com>, "Timothy Rice" <tbrice@gw.dec.state.ny.us>, "jdn@nrc.gov" <jdn@nrc.gov>, "Janicki, John" <JJanick@entergy.com>
Date: 12/19/05 6:22AM
Subject: FW: Picture of Monitoring Well and Storm Drains Affected by Tritium

-----Original Message-----

From: Axelson, William L
Sent: Friday, December 16, 2005 4:27 PM
To: Rutkoske, Michael; Jones, T. R.; Skonieczny, John; Drake, Richard; Nuta, Dragos A; Bode, Paul M.; English, Christopher; Peters, James; Leach, Don; Kulaga, Joe; Morin, Kenneth; McMullin, Kathy; Croulet, Donald; Durfee, Michael; Santis, Hank; Hinrichs, Gary; Quinn, Dennis; Nuta, Dragos A; Lavera, Ron; Thiery, Al; Evers, Bob; Steets, Jim; Colville, Howard J.; Colville, Richard; Gray, Dara; Axelson, William L; Mayer, Don; Loope, Dennis; Sachatello, Ronald
Subject: Picture of Monitoring Well and Storm Drains Affected by Tritium

Gentleman/Ladies:

This is a rough first draft picture from Bill Axelson of the most recent tritium activity in Monitoring Wells and Storm Drain systems.

This picture will be refined in the near future with an upgraded picture and new tritium information as it becomes available.

-----Original Message-----

From: ipcps012@entergy.com [mailto:ipcps012@entergy.com]
Sent: Friday, December 16, 2005 5:10 PM
To: Axelson, William L
Subject: Scan from a Xerox WorkCentre Pro

Please open the attached document. It was scanned and sent to you using a Xerox WorkCentre Pro.

Number of Images: 1
Attachment File Type: PDF

For more information on Xerox products and solutions, please visit <http://www.xerox.com>

A/55

TRITIUM ACTIVITY (12-16-2005)

