

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-02734

Licensee: MALLINCKRODT CHEMICAL WORKS
Site of operation: ST. LOUIS, MO. & HEMATITE PLANT ADDED IN OCT., 58

INFORMATION ON EXACT AMOUNTS OF MATL WAS NOT NEEDED TO EVALUATE

License is nonsuspect because it was superceded by another license

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION
The reason for elimination was: SUPERCEDED BY NEW LICENSE

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0526, BOX 01

Docket 40-00435

Licensee: MALLINCKRODT CHEMICAL WORKS
Address: ST LOUIS MISSOURI Zip:
This license was listed as SUPERCEDED BY ANOTHER LICENSE
Contents of the new license field C-4495 ON 1-1-59
State of operation: MO
Site used: ST. LOUIS, MO. & HEMATITE PLANT ADDED in Oct., 58
Disposition information present: NO DISPOSITION INFORMATION GIVEN
Remarks:
JOB NUMBER: 0526 BOX NUMBER: 01

CONTENTS OF
INVENTORY RECORD IN JOB 0525, BOX 01

Docket

Licensee: MALLINCKRODT CHEMICAL WORKS
Address: 2ND AND MALLINCKRODT STS., ST. LOUIS, MO Zip:
State of operation: MO
Site used: 2ND AND MALLINCKRODT STS., ST. LOUIS
Disposition information present: NO DISPOSITION INFORMATION GIVEN
This license was listed as expired on 09/01/56
Remarks:
JOB NUMBER: 0525 BOX NUMBER: 01

Date of last evaluation/revision: 08/20/92

Reviewer: PAB

A-26