

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-05308

INFORMATION ON EXACT AMOUNTS OF MATL WAS NOT NEEDED TO EVALUATE

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION

The reason for elimination was: SUPERCEDED BY NEW LICENSE

Reviewer's comments concerning license C-05308

Licensee had intended to do some research at the main plant in St. Louis, but the inspection of March, 61, says all activities under this license were conducted at the Hematite site. However, C-5308 resulted from two previous licenses (C-4495 and C-5014) which did have operations in St. Louis. It is a concern that the St. Louis facility will not have a closeout survey due to the site not being included in the superceeding license.

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0276, BOX 02

Docket 40-03719

Licensee: MALLINCKRODT CHEMICAL WORKS

Address: 2ND & MALLINCKRODT ST., ST. LOUIS, MO. Zip:

This license was listed as SUPERCEDED BY ANOTHER LICENSE

Contents of the new license field SMB-293, DOCK. 40-6524 IN 1961

State of operation: MO

Site used: ST. LOUIS, MO. & HEMATITE, MO.

Disposition information present: NO DISPOSITION INFORMATION GIVEN

Remarks: UNITED NUCLEAR CORP. IS THE HOLDER OF LIC. SMB-293

JOB NUMBER: 0276 BOX NUMBER: 02

C-24

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-05014

INVENTORY CONTENTS FOR LICENSE NUMBER: C-05014

Docket 40-03719

Licensee: MALLINCKRODT NUCLEAR CORPORATION

Address: ST LOUIS MISSOURI

Zip:

Description of site: LICENSEE'S ADDRESS & HEMATITE, MO

This license was listed as SUPERCEDED BY ANOTHER LICENSE

Contents of the new license field C-5308

State of operation: MO

Site used: LICENSEE'S ADDRESS & HEMATITE, MO

Disposition information present: NO DISPOSITION INFORMATION GIVEN

Remarks: LICENSE POSSIBLY COVERED BY C-5308

JOB NUMBER: 0276 BOX NUMBER: 02

DESCRIPTION OF ACTIVITY OR FACILITY:

--For evaluation purposes, amounts of the following materials were obtained--

Material--	--Form--	--Amount--	--Unit--
NO INFORMATION ABOUT EXACT MATERIAL AMOUNTS ON FILE			

-
1. License is nonsuspect because it was superceded by another license

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION

The reason for elimination was: SUPERCEDED BY NEW LICENSE

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-04495

INVENTORY CONTENTS FOR LICENSE NUMBER: C-04495

Docket 40-03719

Licensee: MALLINCKRODT NUCLEAR CORPORATION

Address: ST LOUIS MISSOURI

Zip:

Description of site: 2nd & MALLINCKRODT ST IN ST. LOUIS

This license was listed as SUPERCEDED BY ANOTHER LICENSE

Contents of the new license field C-5014

State of operation: MO

Site used: 2nd & MALLINCKRODT ST IN ST. LOUIS + Hematite, Mo.

Disposition information present: NO DISPOSITION INFORMATION GIVEN

Remarks: LICENSE POSSIBLY COVERED BY C-5014

JOB NUMBER: 0276 BOX NUMBER: 02

DESCRIPTION OF ACTIVITY OR FACILITY:

--For evaluation purposes, amounts of the following materials were obtained--

Material--	--Form--	--Amount--	--Unit--
NO INFORMATION ABOUT EXACT MATERIAL AMOUNTS ON FILE			

1. License is nonsuspect because it was superceded by another license
-

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION

The reason for elimination was: SUPERCEDED BY NEW LICENSE