## Closed Generic Communication TACs (PA No. 101122CA/B) Summary Report (01/01/2006 - 03/31/2006)

| TAC NO. | TAC TITLE   | STATUS | AGE       | TAC CLOSED  | LEAD ORG |
|---------|---|--------|-----------|-------------|----------|
| MC5826  | RIS 2005-XX 'Issuance of NUREG-1482, Rev. 1-Guidelines of Inservice Testing At Nucl Pwr Plants'                                   | W      | 14<br>Mon | 01/17/20006 | DCI      |
| MC5858  | RIS 2002-15 'Encryption SGI'  | С      | 14<br>Mon | 02/03/2006  | NSIR     |
| MC7614  | RIS 2005-29 'Anticipated Transients'  | С      | 9<br>Mon  | 02/03/2006  | DSS      |
| MC6734  | RIS 2003-018, Supplement 2, 'Use of Nuclear Energy Institute (NEI) 99-01, Methodology for Development of Emergency Action Levels' | С      |           | 02/02/2006  | NSIR     |
| MC6266  | RIS 2005-30 'Clarification of Post-Fire Safe-Shutdown Circuits Regulator Requirements'  | С      | 13<br>Mon | 02/03/2006  | DRA      |
| MC8995  | RIS 2006-01 'Expiration date for NRC-approved Spent Fuel Transportation Routes'   | С      | 4<br>Mon  | 03/01/2006  | NSIR     |
| MC8777  | RIS 2006-02 'Lessons Learned & Good Practices from Emer. Plan Component of Force-On-Force Exercise'                               | С      | 5<br>Mon  | 03/14/2006  | NSIR     |
| MC9026  | RIS 2006-03 'Guidance for Requesting an Exemption from Bienial EP Exercise Requirements'  | С      | 3<br>Mon  | 03/14/2006  | NSIR     |
| MC6647  | RIS 2006-XX 'Recent Experience from BWR Instability Events'   | W      | 12<br>Mon | 03/15/2006  | DSS      |
| MC7617  | RIS 2006-04 'Alternative Source Term'   | С      | 9<br>Mon  | 03/27/2006  | DRA      |
| MC5657  | GL 2006-02 'Grid Reliabilitly Impact on Plant Risk & Operability of Offsite Power'  | С      | 15<br>Mon | 02/03/2006  | DE       |

Thursday, April 20, 2006 Page 1 of 2

## Closed Generic Communication TACs (PA No. 101122CA/B) Summary Report (01/01/2006 - 03/31/2006)

| TAC NO. | TAC TITLE  | STATUS | AGE      | TAC CLOSED | LEAD ORG |
|---------|--|--------|----------|------------|----------|
| MC8100  | IN 2006-04 'Design Deficiency in Pressurizer Heaters'  | С      | 6<br>Mon | 02/14/2006 | R4       |
| MC9284  | IN 2006-05 'Possible Defect in Bussmann KWN-R'   | С      | 3<br>Mon | 03/09/2006 | DE       |
| MC8529  | IN 2006-08 'Secondary Piping Rupture'  | С      | 5<br>Mon | 03/27/2006 | DCI      |
| MC8827  | IN 2006-06 'Loss of Offsite Power and Station Blackout are More Probable During Summer Period' | С      | 4<br>Mon | 03/27/2006 | DE       |
| MC8341  | BL 'Potential Impact of Chemical Precipitants on Emerg. Recircu. During DBAs at PWRs'          | W      | 7<br>Mon | 03/07/2006 | DCI      |

Thursday, April 20, 2006 Page 2 of 2