From:

Stephen Cohen Oscar Bresnan

To: Date:

5/2/06 1:31PM

Subject:

Re: Tailings Impoundment Liner

Kennecott-Sweetwater-Doctet 40-8584

Oscar:

There are no specific conditions in your current license that specify freeboard or distance above the solution surface. License Condition 9.5 specifies submittals that must be complied with when conducting milling operations. If one of those submittals specifies such a distance or freeboard, then that is the answer. I looked through the 1994 and 2004 license amendment applications, but I didn't see any specific number. If you find something, please let me know.

## Steve

>>> "Oscar Paulson - Bresnan" <oscar.paulson@bresnan.net> 04/27/06 1:35 AM >>> Stepher: Cohen:

George Palochak and I reviewed the previous license (the one prior to the Performance Based License) regarding the tailings impoundment. The pre-Performance Based License stated in License condition 10.7:

The tailings cell liner shall be maintained in an operable condition within 5 feet of the solution surface.

The old license does not use the term "freeboard". When the new Performance Based License was being created, it was agreed that certain conditions in the pre-existing license would be incorporated in to a Standard Operating Procedure (SOP) called Tailings Operating Procedure (TOP) - 1. This language was among several items (including the prohibition against adding more than 25 million gallons per year of pumpback fluid in to the impoundment) included in this Standard Operating Procedure (SOP).

In addition, when the tailings are regraded and the new evaporation ponds constructed, there will be a ten (10) foot wide road of tailings between the fluid in the new pond and the tailings impoundment embankment. This will effectively keep the solution surface ten (10) feet away from the repaired liner.

Given this situation, it would appear that maintaining a five (5) foot slope distance of liner above the top of the road between the new lagoon and the existing embankment should be adequate. Do you agree?

Oscar Paulson Facility Supervisor

CC:

Betty Garrett; Robert Lukes

**Mail Envelope Properties** (44579779.E21 : 13 : 8700)

Subject:

Re: Tailings Impoundment Liner

**Creation Date:** 

5/2/06 1:31PM

From:

Stephen Cohen

Created By:

SJC7@nrc.gov

## Recipients

bresnari.net

oscar.paulson (Oscar Bresnan)

nrc.gov

OWGWPO02.HQGWDO01 BSG CC (Betty Garrett)

nrc.gov

TWGWPO01.HQGWDO01 RGL CC (Robert Lukes)

## Post Office

Route

bresnan.net nrc.gov nrc.gov

OWGWPO02.HQGWDO01 TWGWPO01.HQGWDO01

**Files** 

Size

Date & Time

**MESSAGE** 

2990

05/02/06 01:31PM

**Options** 

**Expiration Date:** 

None

Priority:

Standard

Reply Requested:

No

Return Notification:

None

**Concealed Subject:** 

No

Security:

Standard