

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Eye Lighting Int'l of North America
9150 Hendricks Rd
Mentor, Ohio 44060
REPORT 2006001

2. NRC/REGIONAL OFFICE

US Nuclear Regulatory Comm
2443 Warrenville Rd
Suite 210
Lisle, IL 60532

3. DOCKET NUMBER(S)

030-35694

4. LICENSEE NUMBER(S)

34-23877-01E

5. DATE(S) OF INSPECTION

May 11, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Parker		5/11/06

1591

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Eye Lighting Int'l of North America REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35694	4. LICENSE NUMBER(S) 34-23877-01E	5. DATE(S) OF INSPECTION May 11, 2006	
6. INSPECTION PROCEDURES USED 87125	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03251	2. PRIORITY 5	3. LICENSEE CONTACT Art Kaplan	4. TELEPHONE NUMBER 440/392-3639
<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: 5/2011		
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee is the United States distributor for lamps containing Kr-85. Material is possessed under an Ohio license. These lamps contain krypton as an enhancement to light output. Licensee receives the lamps from its parent firm in Japan for distribution within the United States. The license granted by the NRC is for distribution of the product under a general license and does not authorize possession of material.

Performance Observations

Licensee demonstrated how the lamps are stored and accounted for in its inventory system. Licensee was able to produce its record of the number of units shipped in the past twelve months for the inspector. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

The inspector was able to verify that each unit containing Kr-85 was appropriately embossed indicating that it contained Kr-85. Independent surveys of the lamp storage area indicated minimal results. Licensee personnel are not badged. No violations of requirements were noted.