

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

May 24, 2006

Mr. Klay L. Roberts Radiation Safety Officer Atomic Inspection Labs, Inc. 5620 Modesto NE, Suite A Albuquerque, New Mexico 87113

SUBJECT: NRC INSPECTION REPORT 150-00030/06-001 (FORM 591M)

Dear Mr. Roberts:

This letter refers to the safety inspection conducted on May 8, 2006, at a temporary job site located at the Black Thunder Coal Mine, 6 miles southeast of Wright, Wyoming. This inspection was an examination of activities conducted under the General License provisions contained in 10 CFR 150.20 as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your State of New Mexico Radioactive Material License IR022-23. The preliminary inspection results were discussed with Mr. Bernard Heiman at the conclusion of the onsite inspection. A final telephonic exit briefing was conducted with you on May 22, 2006.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at http://www.nrc.gov/reading-rm/Adams.html.

Should you have any questions concerning this inspection or the enclosed report, please contact me at (817) 860-8217.

Sincerely,

/RA Mark Shaffer for/

Maria C. Maier, Health Physicist Nuclear Materials Inspection Branch

Docket No.: 150-00030 License No.: IR022-23

Enclosure: as stated

cc w/enclosure: New Mexico Radiation Control Program Director Wyoming Radiation Control Program Director Atomic Inspection Labs, Inc.

bcc: (via ADAMS e-mail distribution): LDWert MRShaffer VHCampbell MCMaier LMGersey KEGardin NMIB MIS System RIV Materials Docket Files - 5th Floor

 SUNSI Review Completed:
 MCM1_____ADAMS:
 Yes□ No
 Initials:
 MCM1_____

 Image: Publicly Available
 □
 Non-Publicly Available
 □
 Sensitive
 Image: Non-Sensitive

 DOCUMENT NAME:
 draft:
 s:\dnms\!Nmib\Maier C\60003001AtomicInsp.wpd
 final r:__dnms

RIV:DNMS:NMIB	C:NMIB		
MCMaier	MRShaffer		
/RA MRS for/	/RA/		
05/24/06	05/24/06		
OFFICIAL RECORD COPY	T=Telephone	E=E-mail	F=Fax

			J.S. NUCLEAR REGULATO	RY COMMISSION			
(10-2003) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE/LOCATION	INSPECTED:		2. NRC/REGIONAL OFFICE				
Atomic Inspection Labs, Inc. Temporary job site Black Thunder Coal Mine Wright, Wyoming		USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005					
REPORT NUMBER(S)	2006-001						
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION			
150-00030		IR022-23		May 8 - May 22, 20	08		
LICENSEE:							
The inspection was an examination of the activities conducted under your license as they relate to addition safety and to compliance with the functions of our license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: The inspection of the activities conducted under your license as they relate to addition safety and to compliance with the functions of our license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection consisted of selective examinations of our license. The inspection findings are as follows: Image: The inspection (NEC) rules of the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion. (were self-identified, and corrective Action(s) was/were discussed involving the following requirement(s) and Corrective Action(s): Image: the inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in							
	Licensee'	s Statement of Correct	tive Actions for Item 4	1, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.							
Title	Prin	ted Name	Si	gnature	Date		
LICENSEE'S REPRESENTATIVE							
NRC INSPECTOR	Christi Maier, He	ealth Physicist	/RA Ms	haffer for/	05/24/06		
NRC FORM 591M PART 1	(10-2003)						