



MAY 25 2006

L-PI-06-049
T.S. 5.6.7

U S Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Prairie Island Nuclear Generating Plant Unit 1
Docket 50-282
License No. DPR-42

2006 Unit 1 Steam Generator Inspection Results – 15-Day Report

In accordance with Technical Specification 5.6.7.1, the number of tubes plugged or sleeved in each steam generator (SG) is provided in Table 1.

Table 1 - Prairie Island Unit 1 Refueling Outage 24 Plugs						
Type of Repair	End of Cycle 23		2006 Repairs		Beginning of Cycle 24	
	11 SG	12 SG	11 SG	12 SG	11 SG	12 SG
Tubes Plugged	0	0	0	3	0	3
Tubes Sleeved	0	0	0	0	0	0

Summary of Commitments

This letter contains no new commitments and no revisions to existing commitments.

Thomas J. Palmisano
Site Vice President, Prairie Island Nuclear Generating Plant
Nuclear Management Company, LLC

cc: Administrator, Region III, USNRC
Project Manager, Prairie Island, USNRC
Resident Inspector, Prairie Island, USNRC